

I-26 Station 607+00

- Dimensions: 48" RCP, approximately 384 LF

Observations:

1. Moderate joint separation in pipe, approximately 8 LF from N end. It appears a patch was attempted but has not been successful.
2. Minor joint separation in pipe, approximately 80 LF from N end.

Recommendations:

1. Repair joints showing separation.

I-26 Station 590+00

- Dimensions: Verified 6-foot by 6-foot RCB, Approximately 408 LF
- Observations
 1. Approximately 104-feet (North of entry)-Large crack between panels. Steady flow of water running through crack down walls.
- Recommendations
 1. Repair/seal cracking.