

JULY 22, 2020

# ***Preliminary Pipe Inspection Report***

## ***I-77 Interchange near Exit 82 in York County***





# AET Services

Robotic Inspections

Inspection Date	Mainline Pipe ID	Size	Material	Length	Problems (Y/N)
1/16/2020	EP-1501	15"	RCP	129.6	Yes
1/16/2020	EP-1503	15"	RCP	167.8	Yes
1/16/2020	EP-1850	15"	RCP	113.2	Yes
1/16/2020	EP-1001	18"	RCP	68.8	Yes
1/16/2020	EP-1504	18"	RCP	16.8	No
1/26/2020- 1/27/2020	EP-1801	18"	RCP	101.5	Yes
1/26/2020- 1/27/2020	EP-1802	18"	RCP	194.4	Yes
1/26/2020- 1/27/2020	EP-1803	18"	RCP	210.6	Yes
1/26/2020- 1/27/2020	EP-1804	18"	RCP	211	Yes
1/26/2020- 1/27/2020	EP-1805	18"	RCP	194	Yes
1/26/2020- 1/27/2020	EP-1806	18"	RCP	202	Yes
1/26/2020- 1/27/2020	EP-1807	18"	RCP	186	Yes
1/26/2020- 1/27/2020	EP-1808	18"	RCP	186	Yes
1/26/2020- 1/27/2020	EP-1811	18"	RCP	170.5	Yes
1/26/2020- 1/27/2020	EP-1812	18"	RCP	161.7	Yes
1/26/2020- 1/27/2020	EP-1813	18"	RCP	190.7	Yes
1/26/2020- 1/27/2020	EP-1815	18"	RCP	136.3	Yes
1/26/2020- 1/27/2020	EP-1815.1	18"	RCP	65.2	Yes
1/26/2020- 1/27/2020	EP-1816	18"	RCP	187	Yes
1/26/2020- 1/27/2020	EP-1817	18"	RCP	188	Yes
1/26/2020- 1/27/2020	EP-1818	18"	RCP	195.6	Yes
1/26/2020- 1/27/2020	EP-1819	18"	RCP	186.8	Yes
1/26/2020- 1/27/2020	EP-1820	18"	RCP	179	Yes
1/26/2020- 1/27/2020	EP-1821	18"	RCP	162.4	Yes
1/26/2020- 1/27/2020	EP-1822	18"	RCP	119.3	Yes

1/26/2020- 1/27/2020	EP-1823	18"	RCP	80.3	Yes
1/26/2020- 1/27/2020	EP-1824	18"	RCP	81.2	Yes
1/26/2020- 1/27/2020	EP-1825	18"	RCP	96	Yes
1/26/2020- 1/27/2020	EP-1826	18"	RCP	121.5	Yes
1/26/2020- 1/27/2020	EP-1827	18"	RCP	121.4	Yes
1/26/2020- 1/27/2020	EP-1828	18"	RCP	120	Yes
1/26/2020- 1/27/2020	EP-1829	18"	RCP	176	Yes
1/26/2020- 1/27/2020	EP-1830	18"	RCP	179.2	Yes
1/16/2020	EP-1832	18"	RCP	14.9	Yes
1/16/2020	EP-1833	18"	RCP	88.6	Yes
1/16/2020	EP-1834	18"	RCP	58	Yes
1/16/2020	EP-1835	18"	RCP	31.5	Yes
1/16/2020	EP-1836	18"	RCP	42.8	Yes
1/15/2020	EP-1837	18"	RCP	125.3	Yes
1/15/2020	EP-1838	18"	RCP	321.4	Yes
1/9/2020	EP-1839	18"	RCP	279.7	Yes
1/9/2020	EP-1840	18"	RCP	181.7	Yes
1/9/2020	EP-1841	18"	RCP	49.5	Yes
1/9/2020	EP-1843	18"	RCP	70.8	Yes
1/15/2020	EP-1845.1	18"	RCP	113.9	Yes
1/15/2020	EP-1846	18"	RCP	115.1	Yes
1/15/2020	EP-1847	18"	RCP	119.2	Yes
1/15/2020	EP-1848	18"	RCP	109.8	Yes
1/15/2020	EP-1849	18"	RCP	110.1	Yes
1/16/2020	EP-1851	18"	RCP	112.7	Yes
1/16/2020	EP-1852	18"	RCP	126.6	Yes
1/16/2020	EP-1852.1	18"	RCP	138.4	Yes
1/26/2020- 1/27/2020	EP-2401.2	18"	RCP	97.7	Yes
1/8/2020	Y18.1	18"	RCP	122.3	Yes
1/26/2020- 1/27/2020	EP-1814	24"	RCP	187.1	Yes
1/26/2020- 1/27/2020	EP-2401	24"	RCP	88	Yes
1/16/2020	EP-2402	24"	RCP	54.3	Yes
1/16/2020	EP-2403	24"	RCP	31.2	Yes
1/16/2020	EP-2404	24"	RCP	25.2	Yes
1/16/2020	EP-2405	24"	RCP	128.5	Yes
1/9/2020	EP-2407	24"	RCP	243.8	Yes

1/9/2020	EP-2408	24"	RCP	115.1	Yes
1/9/2020	EP-2409	24"	RCP	18.1	No
1/15/2020	EP-2410	24"	RCP	92.8	Yes
1/15/2020	EP-2411	24"	RCP	114.3	Yes
1/15/2020	EP-2412	24"	RCP	123.9	Yes
1/9/2020	EP-2413	24"	RCP	55.3	Yes
1/16/2020	EP-2414	24"	RCP	47.9	Yes
1/16/2020	EP-2415	24"	RCP	65.8	Yes
1/16/2020	EP-2416	24"	RCP	68.8	Yes
1/16/2020	EP-3001	24"	RCP	80.3	Yes
1/16/2020	EP-3002	30"	RCP	85.9	Yes
1/16/2020	EP-3600	36"	RCP	98.1	Yes
1/26/2020- 1/27/2020	EP-3601	36"	RCP	96.1	Yes
1/16/2020	EP-3602	36"	RCP	58.1	Yes
1/16/2020	EP-3603	36"	RCP	36.4	Yes
1/8/2020	EP-42.1	42"	RCP	290.8	Yes
1/16/2020	EP-4803	48"	RCP	63.8	Yes
1/15/2020	EP-4804	48"	RCP	133	Yes
1/15/2020	EP-4805	48"	RCP	126.2	Yes
1/15/2020	EP-4806	48"	RCP	291.3	Yes
1/15/2020	EP-4807	48"	RCP	324.5	Yes
1/15/2020	EP-4808	48"	RCP	310.3	Yes
1/16/2020	EP-4809	48"	RCP	233.5	Yes
1/16/2020	EP-4810	48"	RCP	217.2	Yes
1/16/2020	EP-6001	60"	RCP	40	Yes
1/16/2020	EP-6002	60"	RCP	44.1	Yes
1/16/2020	EP-6003	60"	RCP	17	Yes
1/16/2020	EP-6004	60"	RCP	12	No
1/16/2020	EP-4811	72"	RCP	85	Yes
1/9/2020	EP-8401	84"	RCP	165	Yes
1/9/2020	EP-8402	84"	RCP	160	Yes

\*\*\*The following pipes could not be inspected due to debris inside the pipes. Images included below.

Needs Cleaning	EP-1200	12"	RCP		
Needs Cleaning	EP-1500	15"	CMP		
Needs Cleaning	EP-1809	18"	RCP		
Needs Cleaning	EP-1810	18"	RCP		
Needs Cleaning	EP-1831	18"	RCP		
Needs Cleaning	EP-1842	18"	RCP		
Needs Cleaning	ECMP-1800	18"	CMP		
Needs Cleaning	EDPI-3600	36"	DIP		
Needs Cleaning	EP-3601 End	36"	RCP		
Needs Cleaning	EP-4801	48"	RCP		
Needs Cleaning	ECMP-4800	48"	CMP		

EP-1200



EP-1500



EP-1809



EP-1810



EP-1831



**No images available for EP-1842.**

ECMP-1800- Could not be accessed due to muddy access road.



EDPI-3600



EP-3601 End



ECMP-4800




EP-4801



**EP-1501**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1501</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 2:57 PM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>15.0 in.</b>	<b>15.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1501**

Start date/time:  
**1/16/2020 2:57 PM**

Direction:  
**Against the flow**

Weather:  
**Dry**



## Main Inspections Small Photos


Mainline ID: <b>EP-1501</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 2:57 PM</b>	Asset length: <b>129.6 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXDI-1501</b>	Depth US:	Downstream node: <b>EXDI-1502</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>15.0 in.</b>	Pipe width: <b>15.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
6.6 ft.	U		/ Grouted			



14.8 ft.	U		/ Joint Offset			
----------	---	--	----------------	--	--	--




# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

14.8 ft. U / Joint - Gasket



23.0 ft. U / Joint Offset



31.3 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

39.3 ft. U / Joint Offset



40.6 ft. U / Crack




47.5 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

53.7 ft. U 7 / Crack



55.6 ft. U / Joint Offset




63.8 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

71.9 ft. U / Joint Offset



80.1 ft. U / Joint Offset



88.1 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

96.3 ft. U / Joint Offset



96.3 ft. U / Joint - Gasket



104.4 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

112.4 ft. U / Joint Offset




120.7 ft. U / Joint Offset



129.6 ft. U / End of Pipe




## Inspection's photos



**EP-1503**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1503</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 2:24 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>15.0 in.</b>	<b>15.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1503**

Start date/time:  
**1/16/2020 2:24 PM**

Direction:  
**With the flow**

Weather:  
**Dry**




Project name:  
**York County**

Mainline ID:  
**EP-1503**

Start date/time:  
**1/16/2020 2:24 PM**

Direction:  
**With the flow**

Weather:  
**Dry**



Project name:  
**York County**


Mainline ID:  
**EP-1503**

Start date/time:  
**1/16/2020 2:24 PM**

Direction:  
**With the flow**

Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1503</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 2:24 PM</b>	Asset length: <b>167.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXDI-1502</b>	Depth US:	Downstream node: <b>EXDI-1503</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>15.0 in.</b>	Pipe width: <b>15.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.7 ft.	D		/	Joint			



6.7 ft.	D		1 /	Broken			Chip
---------	---	--	-----	--------	--	--	------



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

**14.9 ft.    D                                    /    Joint**




**23.0 ft.    D                                    /    Joint**



**23.0 ft.    D                                    7 / 9   Broken**

**Chip**




**31.3 ft.    D                                    /    Joint Offset**



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

39.5 ft. D / Joint Offset



39.5 ft. D 3 / Crack



39.5 ft. D / Joint - Gasket



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

39.5 ft. D 10 / Broken



47.6 ft. D / Joint Offset



55.8 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


63.8 ft. D / Joint Offset



63.8 ft. D / Joint - Gasket



71.9 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

71.9 ft. D / Joint - Gasket




80.2 ft. D / Joint Offset

88.2 ft. D / Joint Offset



89.7 ft. D 3 / Crack



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

95.0 ft. D 9 / Crack



96.2 ft. D 10 / Crack



96.5 ft. D / Joint Offset



103.5 ft. D 9 / Crack

# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


104.4 ft. D / Joint Offset



104.5 ft. D 11 / 1 Broken



112.6 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

112.6 ft. D 7 / 12 Broken



112.6 ft. D 11 / Rebar Showing




120.7 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


120.7 ft. D 5 / Joint - Gasket



129.0 ft. D / Joint Offset




137.0 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

**137.0 ft. D                      3 /      Crack**



**145.4 ft. D                      /      Joint Offset**

**153.6 ft. D                      /      Joint Offset**



**153.6 ft. D                      /      Joint - Gasket**



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

161.6 ft. D / Joint Offset



161.6 ft. D / Joint - Gasket



161.6 ft. D 5 / Broken




167.8 ft. D / End of Pipe

## Inspection's photos

**EP-1850**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1850</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 10:40 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1850**

Start date/time:  
**1/16/2020 10:40 AM**

Direction:  
**Against the flow**

Weather:  
**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1850</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 10:40 AM</b>	Asset length: <b>113.2 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXDI-34</b>	Depth US:	Downstream node: <b>EXCB-1820</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.6 ft.	U		/	Joint			



14.7 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

22.8 ft. U / Joint Offset



22.8 ft. U 9 / Crack



31.1 ft. U / Joint Offset



# Observations

Distance	Dir. Length	From/To Code	Modifier/Severity	Rating	Comments
----------	-------------	--------------	-------------------	--------	----------

**31.1 ft. U 9 / Crack**



**39.2 ft. U / Joint**



**39.2 ft. U 11 / Broken**



**Chip**

# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

47.3 ft. U / Joint



55.6 ft. U / Joint




63.6 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

71.9 ft. U / Joint Offset Misaligned



79.9 ft. U / Joint Offset Misaligned



88.1 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

96.1 ft. U / Joint Offset Misaligned



104.4 ft. U / Joint Offset



113.2 ft. U / End of Pipe




## Inspection's photos



**EP-1001**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1001</b>	<b>Rock Hill</b>	<b>Corporate Blvd</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 3:59 PM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-1001**

Start date/time:  
**1/16/2020 3:59 PM**

Direction:  
**Against the flow**

Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1001</b>	City: <b>Rock Hill</b>	Address: <b>Corporate Blvd</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 3:59 PM</b>	Asset length: <b>68.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>OP-101</b>	Depth US:	Downstream node: <b>OP-102</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

## Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
2.3 ft.	U		/	Joint			



2.3 ft.	U		6 /	Broken			
---------	---	--	-----	--------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

2.3 ft. U / Joint - Gasket



---

2.3 ft. U 6 / Joint - Infiltration



---

2.3 ft. U 1 / Broken




Chip

# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

8.6 ft. U / Joint



8.7 ft. U 10 / 2 Joint - Gasket



17.0 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

24.9 ft. U / Joint



33.3 ft. U / Joint



41.4 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

50.0 ft. U / Joint



58.1 ft. U / Joint



66.0 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

66.0 ft. U 5 / 7 Broken



68.8 ft. U / End of Pipe




## Inspection's photos



**EP-1504**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1504</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 12:01 PM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



## Main Inspections Small Photos


Mainline ID: <b>EP-1504</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 12:01 PM</b>	Asset length: <b>16.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1818</b>	Depth US:	Downstream node: <b>EXDI-35</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
7.9 ft.	U		/	Joint			



16.8 ft.	U		/	End of Pipe			
----------	---	--	---	-------------	--	--	--




## Inspection's photos




**EP-1801**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1801</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>101.5</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 101.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 101.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 101.5	Operator: Alex Barlet	Comments:




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 101.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 101.5	Operator: Alex Barlet		




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments:
Surveyed footage: 101.5	Operator: Alex Barlet		




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 101.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 101.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1801</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>101.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 101.5	Operator: Alex Barlet		



Project Name: <b>York County</b>	Mainline ID: <b>EP1801</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>101.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1801	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 101.5	Operator: Alex Barlet		




**EP-1802**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1802</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>194.4</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.4	Operator: Alex Barlet	Comments:




Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 194.4	Operator: Alex Barlet		




Project Name: <b>York County</b>	Mainline ID: <b>EP1802</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>194.4</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1802</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>194.4</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.4	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.4	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1802</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>194.4</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.4	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.4	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 194.4	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1802</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>194.4</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1802	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.4	Operator: Alex Barlet	Comments




**EP-1803**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1803.</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>210.6</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1803.</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>210.6</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1803.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 210.6	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1803.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 210.6	Operator: Alex Barlet		




Project Name: York County	Mainline ID: EP1803.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 210.6	Operator: Alex Barlet		




Project Name: <b>York County</b>	Mainline ID: <b>EP1803.</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>210.6</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1803.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 210.6	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1803.</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>210.6</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1803.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 210.6	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1803.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 210.6	Operator: Alex Barlet		




Project Name: York County	Mainline ID: EP1803.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 210.6	Operator: Alex Barlet	Comments




**EP-1804**

## Main Inspection with Pipe-Run Graph and Images


Project Name: York County	Mainline ID: EP1804.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 211.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1804.</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>211.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1804.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 211.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1804.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 211.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1804.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 211.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1804.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 211.5	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1804.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 211.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1804.</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>211.5</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: York County	Mainline ID: EP1804.	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 211.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1804.</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>211.5</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1805**

## Main Inspection with Pipe-Run Graph and Images


Project Name: York County	Mainline ID: EP-1805	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP-1805</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>194.0</b>	Operator: <b>Alex Barlet</b>		




Project Name: <b>York County</b>	Mainline ID: <b>EP-1805</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>194.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP-1805</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>194.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP-1805</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>194.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP-1805	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 194.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP-1805</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>194.0</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP-1805	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 194.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP-1805</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>194.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP-1805	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.0	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP-1805</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>194.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP-1805	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 194.0	Operator: Alex Barlet	Comments




**EP-1806**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1806.</b>		City: <b>YORK, SC</b>		Address: <b>177-NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>202.1</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1806.	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 202.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1806.	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 202.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1806.	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 202.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: York County	Mainline ID: EP1806.	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 202.1	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1806.</b>	City: <b>YORK, SC</b>	Address: <b>177-NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>202.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1806.	City: YORK, SC	Address: 177-NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 202.1	Operator: Alex Barlet		




**EP-1807**

## Main Inspection with Pipe-Run Graph and Images

Project Name: <b>York County</b>		Mainline ID: <b>EP1807</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>186.0</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1807	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1807	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1807</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1807	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1807</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1807</b>	City: <b>York, SC</b>	Address: <b>I77 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1807	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1807	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1807	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1807	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1807</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.0</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1808**

## Main Inspection with Pipe-Run Graph and Images

Project Name: <b>York County</b>		Mainline ID: <b>EP1808</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>186.0</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1808</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1808</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1808</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1808	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1808	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1808	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1808	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1808	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: Downstream	Surveyed footage: 186.0	Operator: Alex Barlet	Comments




**EP-1811**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1811</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>170.5</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1811	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Light Rain
Direction: Downstream	Surveyed footage: 170.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1811	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: Downstream	Surveyed footage: 170.5	Operator: Alex Barlet	Comments:




Project Name: York County	Mainline ID: EP1811	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: Downstream	Surveyed footage: 170.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments:




Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1811</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>170.5</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1812**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1812</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>161.7</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1812	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 161.7	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1812	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 161.7	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1812</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>161.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1812	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 161.7	Operator: Alex Barlet	Comments:




Project Name: <b>York County</b>	Mainline ID: <b>EP1812</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>161.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1812	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 161.7	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1812	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 161.7	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1812</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>161.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1812	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 161.7	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1812</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>161.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1812</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>161.7</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1813**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1813</b>		City: <b>YORK, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>190.7</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1813</b>	City: <b>YORK, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments
Surveyed footage: <b>190.7</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP1813	City: YORK, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 190.7	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1813	City: YORK, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 190.7	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1813	City: YORK, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 190.7	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1813</b>	City: <b>YORK, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>190.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1813	City: YORK, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 190.7	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1813	City: YORK, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 190.7	Operator: Alex Barlet	Comments:




Project Name: York County	Mainline ID: EP1813	City: YORK, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 190.7	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1813</b>	City: <b>YORK, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>190.7</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1813</b>	City: <b>YORK, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>190.7</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1813</b>	City: <b>YORK, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>190.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1813</b>	City: <b>YORK, SC</b>	Address: <b>I77 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>190.7</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1815**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1815</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>136.3</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1815	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 136.3	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1815	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 136.3	Operator: Alex Barlet	Comments:




Project Name: York County	Mainline ID: EP1815	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 136.3	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1815</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>136.3</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1815</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>136.3</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1815</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>136.3</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1815</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>136.3</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1815</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>136.3</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1815	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments:
Surveyed footage: 136.3	Operator: Alex Barlet		




**EP-1815.1**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1815.1</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>65.2</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1815.1</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>65.2</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1815.1	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: UPSTREAM	Surveyed footage: 65.2	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1815.1	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: UPSTREAM	Surveyed footage: 65.2	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1815.1</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>65.2</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1815.1</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>65.2</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1816**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>	Surface condition: <b></b>
		Weather: <b>Dry</b>	Comments: <b></b>




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b></b>	Weather: <b>Dry</b>	Comments: <b></b>
Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>		




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>	Surface condition: <b></b>
			Weather: <b>Dry</b>
		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>	Surface condition: <b></b>
			Weather: <b>Dry</b>
Comments			




Project Name: York County	Mainline ID: EP1816	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surveyed footage: 187.1	Operator: Alex Barlet	Surface condition: Weather: Dry
Comments			




Project Name: York County	Mainline ID: EP1816	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surveyed footage: 187.1	Operator: Alex Barlet	Surface condition: Weather: Dry
Comments			




Project Name: York County	Mainline ID: EP1816	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surveyed footage: 187.1	Operator: Alex Barlet	Surface condition: Weather: Dry
Comments			




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>	Surface condition: <b></b>
			Weather: <b>Dry</b>
		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>	Surface condition: <b></b>
			Weather: <b>Dry</b>
		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b></b>	Weather: <b>Dry</b>	Comments: <b></b>
Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>		




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>I77 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>	Surface condition: <b></b>
			Weather: <b>Dry</b>
Comments			




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b></b>	Weather: <b>Dry</b>	Comments: <b></b>
Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP1816	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surveyed footage: 187.1	Operator: Alex Barlet	Surface condition: Weather: Dry
Comments			



Project Name: York County	Mainline ID: EP1816	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surveyed footage: 187.1	Operator: Alex Barlet	Surface condition: Weather: Dry
Comments			




Project Name: <b>York County</b>	Mainline ID: <b>EP1816</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b></b>	Weather: <b>Dry</b>	Comments: <b></b>
Surveyed footage: <b>187.1</b>	Operator: <b>Alex Barlet</b>		




**EP-1817**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1817</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>188.0</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1817	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 188.0	Operator: Alex Barlet	Comments:




Project Name: York County	Mainline ID: EP1817	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 188.0	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1817	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 188.0	Operator: Alex Barlet	Comments:




Project Name: York County	Mainline ID: EP1817	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 188.0	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1817	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 188.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1817</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>188.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1817</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>188.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1817</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>188.0</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: York County	Mainline ID: EP1817	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 188.0	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1817</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>188.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1817	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 188.0	Operator: Alex Barlet	Comments




**EP-1818**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1818</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>195.6</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1818</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>195.6</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1818	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 195.6	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1818	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 195.6	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1818	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 195.6	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1818</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>195.6</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1818</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>195.6</b>	Operator: <b>Alex Barlet</b>		




Project Name: <b>York County</b>	Mainline ID: <b>EP1818</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments
Surveyed footage: <b>195.6</b>	Operator: <b>Alex Barlet</b>		



Project Name: York County	Mainline ID: EP1818	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 195.6	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1818	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 195.6	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1818	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 195.6	Operator: Alex Barlet	Comments:



Project Name: York County	Mainline ID: EP1818	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 195.6	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1818</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>195.6</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1819**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1819</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>186.8</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1819</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.8</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1819	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.8	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1819	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.8	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1819	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.8	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1819	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.8	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1819</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.8</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1819	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.8	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1819	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.8	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1819	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 186.8	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1819</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.8</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1819</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>186.8</b>	Operator: <b>Alex Barlet</b>	Comments:



**EP-1820**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1820</b>		City: <b>ROCK HILL, SC</b>		Address: <b>I77NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>179.0</b>		Operator: <b>Adam Knight</b>		Comments	




Project Name: York County	Mainline ID: Y-EP1820	City: ROCK HILL, SC	Address: 177NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 179.0	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1820</b>	City: <b>ROCK HILL, SC</b>	Address: <b>I77NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>179.0</b>	Operator: <b>Adam Knight</b>		




Project Name: York County	Mainline ID: Y-EP1820	City: ROCK HILL, SC	Address: 177NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 179.0	Operator: Adam Knight	Comments




Project Name: York County	Mainline ID: Y-EP1820	City: ROCK HILL, SC	Address: 177NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 179.0	Operator: Adam Knight	Comments




Project Name: York County	Mainline ID: Y-EP1820	City: ROCK HILL, SC	Address: 177NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 179.0	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1820</b>	City: <b>ROCK HILL, SC</b>	Address: <b>I77NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>179.0</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1820</b>	City: <b>ROCK HILL, SC</b>	Address: <b>I77NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>179.0</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: York County	Mainline ID: Y-EP1820	City: ROCK HILL, SC	Address: 177NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 179.0	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1820</b>	City: <b>ROCK HILL, SC</b>	Address: <b>I77NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>179.0</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1820</b>	City: <b>ROCK HILL, SC</b>	Address: <b>I77NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>179.0</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: York County	Mainline ID: Y-EP1820	City: ROCK HILL, SC	Address: 177NB
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 179.0	Operator: Adam Knight	Comments



**EP-1821**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1821</b>		City: <b>ROCK HILL, SC</b>		Address: <b>177NB MEDIAN</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>162.4</b>		Operator: <b>Adam Knight</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1821</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>162.4</b>	Operator: <b>Adam Knight</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1821</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>162.4</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1821</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>162.4</b>	Operator: <b>Adam Knight</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1821</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>162.4</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1821</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>162.4</b>	Operator: <b>Adam Knight</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1821</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>162.4</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1821</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>162.4</b>	Operator: <b>Adam Knight</b>	Comments




**EP-1822**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1822</b>		City: <b>ROCK HILL, SC</b>		Address: <b>177NB MEDIAN</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>119.4</b>		Operator: <b>Adam Knight</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1822</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>119.4</b>	Operator: <b>Adam Knight</b>	Comments:




Project Name: York County	Mainline ID: Y-EP1822	City: ROCK HILL, SC	Address: 177NB MEDIAN
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 119.4	Operator: Adam Knight	Comments




Project Name: York County	Mainline ID: Y-EP1822	City: ROCK HILL, SC	Address: 177NB MEDIAN
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 119.4	Operator: Adam Knight	Comments




Project Name: York County	Mainline ID: Y-EP1822	City: ROCK HILL, SC	Address: 177NB MEDIAN
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 119.4	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1822</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>119.4</b>	Operator: <b>Adam Knight</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1822</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>119.4</b>	Operator: <b>Adam Knight</b>	Comments:




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1822</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>119.4</b>	Operator: <b>Adam Knight</b>	Comments




**EP-1823**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1823</b>		City: <b>ROCK HILL, SC</b>		Address: <b>177NB MEDIAN</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>80.3</b>		Operator: <b>Adam Knight</b>		Comments	



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1823</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>80.3</b>	Operator: <b>Adam Knight</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1823</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>80.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1823</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>80.3</b>	Operator: <b>Adam Knight</b>	Comments






Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1823</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>80.3</b>	Operator: <b>Adam Knight</b>	Comments




**EP-1824**

## Main Inspection with Pipe-Run Graph and Images

Project Name: <b>York County</b>		Mainline ID: <b>EP1824</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/26/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>81.2</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1824	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: UPSTREAM	Surveyed footage: 81.2	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1824</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>81.2</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1824</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>81.2</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1825**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1825</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/26/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>96.1</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP1825</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1825</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: York County	Mainline ID: EP1825	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1825</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1826**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1826</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/26/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>121.5</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1826	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 121.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1826</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>121.5</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1826	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 121.5	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1826	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 121.5	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1826</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>121.5</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1827**

## Main Inspection with Pipe-Run Graph and Images


Project Name: York County	Mainline ID: EP1827	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 121.4	Operator: Alex Barlet		




Project Name: <b>York County</b>	Mainline ID: <b>EP1827</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>121.4</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP1827	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 121.4	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1827</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>121.4</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: York County	Mainline ID: EP1827	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 121.4	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1827</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>121.4</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1828**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1828</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/26/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>120.0</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP1828	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 120.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1828</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>120.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1828	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 120.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1828</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>120.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1828	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 120.0	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1828	City: York, SC	Address: 177 NB
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 120.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1828</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>120.0</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-1829**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1829</b>		City: <b>Rock Hill, SC</b>		Address: <b>177 NB median</b>	
Start date/time: <b>1/26/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>176.3</b>		Operator: <b>Adam Knight</b>		Comments	




Project Name: York County	Mainline ID: Y-EP1829	City: Rock Hill, SC	Address: 177 NB median
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: UPSTREAM	Surveyed footage: 176.3	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: York County	Mainline ID: Y-EP1829	City: Rock Hill, SC	Address: 177 NB median
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: UPSTREAM	Surveyed footage: 176.3	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1829</b>	City: <b>Rock Hill, SC</b>	Address: <b>177 NB median</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>176.3</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: York County	Mainline ID: Y-EP1829	City: Rock Hill, SC	Address: 177 NB median
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 176.3	Operator: Adam Knight	Comments




**EP-1830**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1830</b>		City: <b>ROCK HILL, SC</b>		Address: <b>177NB MEDIAN</b>	
Start date/time: <b>1/26/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>		Comments		



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: York County	Mainline ID: Y-EP1830	City: ROCK HILL, SC	Address: 177NB MEDIAN
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: UPSTREAM	Surveyed footage: 179.2	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: York County	Mainline ID: Y-EP1830	City: ROCK HILL, SC	Address: 177NB MEDIAN
Start date/time: 1/26/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 179.2	Operator: Adam Knight	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>UPSTREAM</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>		



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>177NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1830</b>	City: <b>ROCK HILL, SC</b>	Address: <b>I77NB MEDIAN</b>
Start date/time: <b>1/26/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>179.2</b>	Operator: <b>Adam Knight</b>	Comments



**EP-1832**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1832</b>	<b>Rock Hill</b>	<b>Celriver Rd</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 10:06 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



## Main Inspections Small Photos

Mainline ID: <b>EP-1832</b>	City: <b>Rock Hill</b>	Address: <b>Celriver Rd</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 10:06 AM</b>	Asset length: <b>14.9 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-2404</b>	Depth US:	Downstream node: <b>OP-1832</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
7.5 ft.	U		/	Joint			



7.5 ft.	U		/	Broken			Chip
---------	---	--	---	--------	--	--	------




# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
14.9 ft.	U		/	Abandoned Survey		



---


## Inspection's photos



**EP-1833**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1833</b>	<b>Rock Hill</b>	<b>Riverwalk Pwy</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 8:21 AM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-1833**

Start date/time:  
**1/16/2020 8:21 AM**

Direction:  
**With the flow**

Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1833</b>	City: <b>Rock Hill</b>	Address: <b>Riverwalk Pwy</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 8:21 AM</b>	Asset length: <b>88.6 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1801</b>	Depth US:	Downstream node: <b>EXCB-1833</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.8 ft.	D		/	Joint			



15.2 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

23.2 ft. D / Joint



31.4 ft. D / Joint



39.4 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------


47.6 ft. D / Joint



55.4 ft. D / Joint



63.7 ft. D / Joint Offset




# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

63.7 ft. D 12 / Broken



71.7 ft. D / Joint Offset




79.8 ft. D / Joint Offset



## Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

84.6 ft.    D                    12 / 12    Crack



88.6 ft.    D                    /        End of Pipe




## Inspection's photos



**EP-1834**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1834</b>	<b>Rock Hill</b>	<b>Riverwalk Pwy</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 8:09 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



## Main Inspections Small Photos

Mainline ID: <b>EP-1834</b>	City: <b>Rock Hill</b>	Address: <b>Riverwalk Pwy</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 8:09 AM</b>	Asset length: <b>58.0 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1802</b>	Depth US:	Downstream node: <b>EXCB-1801</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

## Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.7 ft.	U		/	Joint			



14.7 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

22.8 ft. U / Joint



30.9 ft. U / Joint



39.0 ft. U / Joint




# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

47.2 ft. U / Joint



47.2 ft. U 8 / 10 Broken



55.3 ft. U / Joint






**EP-1835**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1835</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 7:28 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



## Main Inspections Small Photos

Mainline ID: <b>EP-1835</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 7:28 AM</b>	Asset length: <b>31.5 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1803</b>	Depth US:	Downstream node: <b>EXCB-1805</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.5 ft.	U		/	Joint			



14.8 ft.	U		/	Joint Offset			
----------	---	--	---	--------------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


23.0 ft. U / Joint Offset



31.5 ft. U / End of Pipe




## Inspection's photos



**EP-1836**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1836</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 7:36 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



## Main Inspections Small Photos

Mainline ID: <b>EP-1836</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 7:36 AM</b>	Asset length: <b>42.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1804</b>	Depth US:	Downstream node: <b>EXCB-1803</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
8.3 ft.	U		/	Joint			



16.4 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

24.9 ft. U / Joint



32.8 ft. U / Joint



40.8 ft. U / Joint




# Observations

Distance	Dir. Length	From/To Code	Modifier/Severity	Rating	Comments
42.8 ft.	U	/	End of Pipe		




## Inspection's photos



**EP-1837**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1837</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 2:45 PM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-1837**

Start date/time:  
**1/15/2020 2:45 PM**

Direction:  
**Against the flow**

Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1837</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 2:45 PM</b>	Asset length: <b>125.3 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-1837</b>	Depth US:	Downstream node: <b>EX-CB-1805</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.8 ft.	U		/	Joint			



14.8 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

22.9 ft. U / Joint



29.7 ft. U 6 / Debris



30.9 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

39.1 ft. U / Joint



47.2 ft. U / Joint



55.5 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

63.7 ft. U / Joint



71.8 ft. U / Joint



80.0 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

88.2 ft. U / Joint



96.2 ft. U / Joint



104.2 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

112.5 ft. U / Joint




120.4 ft. U / Joint



125.3 ft. U / End of Pipe




## Inspection's photos



**EP-1838**

## Main Inspection with Pipe-Run Graph

Project Name: <b>York County</b>		Mainline ID: <b>Y-EP-1838</b>		City: <b>Rock Hill, SC</b>		Address: <b>Paragon Way</b>	
Start date/time: <b>1/9/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>53.4</b>		Operator: <b>Adam Knight</b>		Comments:	



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP-1838	Project Name: York County	Start date/time: 1/9/2020 9:51:48 AM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXCB1806	Depth US:	Downstream node: EXCB1807	Depth DS:	Asset length: 53.4	Extra:
Comments					

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
7.0	joint		Yes	/		
						
8.2	6.8	Crack -Major	Yes	5 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
			15.0	joint	Yes	/
			23.0	joint	Yes	/
			23.0	16.2	Crack -Major	Yes 5 /

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
24.0		Surface Damage	Yes	3 /		
						
30.9	joint		Yes	/		
						
						
39.1	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
39.2		Root-in-Joint	Yes	5 /		
						
47.2	joint		Yes	/		
						
53.4		End of Pipe	Yes	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
53.4	STOP		Yes	/		

**EP-1838.1**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1838</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 3:08 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-1838**

Start date/time:  
**1/15/2020 3:08 PM**

Direction:  
**With the flow**

Weather:

**Dry**




Project name:  
**York County**

Mainline ID:  
**EP-1838**

Start date/time:  
**1/15/2020 3:08 PM**

Direction:  
**With the flow**

Weather:  
**Dry**




Project name:  
**York County**

Mainline ID:  
**EP-1838**

Start date/time:  
**1/15/2020 3:08 PM**

Direction:  
**With the flow**

Weather:  
**Dry**



Project name:  
**York County**

Mainline ID:  
**EP-1838**

Start date/time:  
**1/15/2020 3:08 PM**

Direction:  
**With the flow**

Weather:

**Dry**

Mainline length: 321.4 ft.  
Surveyed length: 321.4 ft.



## Main Inspections Small Photos

Mainline ID: <b>EP-1838</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 3:08 PM</b>	Asset length: <b>321.4 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-1805</b>	Depth US:	Downstream node: <b>EX-CB-1805.1</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
3.8 ft.	D		/ Joint Offset			



11.6 ft.	D		/ Joint Offset			
----------	---	--	----------------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

19.7 ft. D / Joint



28.1 ft. D / Joint Offset



36.2 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

44.3 ft. D / Joint Offset



52.4 ft. D / Joint Offset



60.6 ft. D / Joint Offset

Misaligned



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

68.7 ft. D / Joint Offset



76.9 ft. D / Joint Offset



84.9 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

93.1 ft. D / Joint Offset



101.2 ft. D / Joint Offset



101.2 ft. D 12 / 3 Joint - Gasket



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

109.3 ft. D / Joint Offset



109.3 ft. D 12 / 2 Joint - Gasket



117.5 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


125.6 ft. D / Joint Offset



125.6 ft. D 12 / 1 Joint - Gasket



133.6 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

141.9 ft. D / Joint



149.9 ft. D / Joint Offset



158.0 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

166.3 ft. D / Joint Offset



174.5 ft. D / Joint




182.5 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

190.6 ft. D / Joint Offset



198.9 ft. D / Joint Offset



207.1 ft. D / Joint Offset

Misaligned



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

215.1 ft. D / Joint Offset



223.2 ft. D / Joint Offset



223.2 ft. D 5 / Broken Chip



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

231.4 ft. D / Joint



239.5 ft. D / Joint



239.5 ft. D 2 / Broken



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

247.9 ft. D / Joint Offset



255.8 ft. D / Joint



263.9 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

272.1 ft. D / Joint Offset



280.2 ft. D / Joint Offset



288.4 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

288.4 ft. D 5 / Broken



296.5 ft. D / Joint Offset



304.6 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

313.1 ft. D / Joint Offset



321.4 ft. D / End of Pipe




## Inspection's photos




**EP-1839**

## Main Inspection with Pipe-Run Graph


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1839</b>		City: <b>ROCK HILL, SC</b>		Address: <b>PARAGON WAY</b>	
Start date/time: <b>1/9/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>	Weather: <b>Dry</b>		
Direction: <b>Downstream</b>	Surveyed footage: <b>279.7</b>		Operator: <b>Adam Knight</b>		Comments:		



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1839</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>279.7</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1839</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>279.7</b>	Operator: <b>Adam Knight</b>	Comments:



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP1839	Project Name: York County	Start date/time: 1/9/2020 10:06:55 AM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXCB1807	Depth US:	Downstream node: EXCB1808	Depth DS:	Asset length: 279.7	Extra:

Comments

---


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
6.4		joint	No	/		
						
6.5		Crack- Minor	No	9 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	14.3	joint	No	/		
 	22.1	Joint Offset	No	/		
 	30.5	Joint Offset	No	/		


## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
38.4	Joint Offset	No	/			
						
46.2	joint	No	/			
						
46.2	Crack	No	12 /			

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
54.6		joint	No	/		
						
						
54.6	152.6	Crack -Major	No	12 /		
						
62.5		Joint Offset	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
70.4	joint		No	/		
						
78.3	joint		No	/		
						
86.4	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
94.2	joint		No	/		
						
94.2	chip		No	/		
						
102.5	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
110.4		Joint-Misalign ed	No	/		
						
118.4		Joint Offset	No	/		
						
126.5		joint	No	/		

### Observations


Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
134.6	joint		No	/		
						
142.8	Joint Offset		No	/		
						
150.6	joint		No	/		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
183.0		Joint Offset	No	/		
						
191.1		Joint Offset	No	/		
						
199.1		Joint Offset	No	/		

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
<div style="display: flex; justify-content: space-around;">   </div>						
207.2		Joint Offset	No	/		
<div style="display: flex; justify-content: space-around;">   </div>						
215.4		Joint Offset	No	/		
<div style="display: flex; justify-content: space-around;">   </div>						
215.5	56.1	Crack -Major	No	12 /		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
223.5	joint		No	/		
						
						
231.4	joint		No	/		
						
						
239.5	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
247.5	joint		No	/		
						
255.5	joint		No	/		
						
263.6	Joint-Misaligned		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
271.6		Joint -Misaligned	No	/		
						
271.6	chip		No	4 /		
						
279.7		End of Pipe	No	/		

AET Services  
623 Rices Creek Road  
Liberty, SC 29657  
1-844-8TOPGUN  
www.aettopgun.com


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
279.7	STOP	No	/			


**EP-1840**

# Main Inspection with Pipe-Run Graph


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1840</b>		City: <b>ROCK HILL, SC</b>		Address: <b>PARAGON WAY</b>	
Start date/time: <b>1/9/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>181.7</b>		Operator: <b>Adam Knight</b>		Comments:	



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1840</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>181.7</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1840</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Sidewalk</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>181.7</b>	Operator: <b>Adam Knight</b>	Comments:



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com


## Observation Report with Still Images

Mainline ID: Y-EP1840	Project Name: York County	Start date/time: 1/9/2020 10:58:44 AM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXCB1808	Depth US:	Downstream node: EXCB1809	Depth DS:	Asset length: 181.7	Extra:

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
<div style="display: flex; justify-content: space-between;"> <div style="width: 25%;">  </div> <div style="width: 75%;"></div> </div>						
3.7	joint		No	/		
<div style="display: flex; justify-content: space-around;"> <div style="width: 48%;">  </div> <div style="width: 48%;">  </div> </div>						
11.8	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
19.7	joint		No	/		
						
27.9	Joint Offset		No	/		
						
35.8	Joint Offset		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
44.0		Joint Offset	No	/		
						
44.0		Crack	No	11 /		
						
51.7		Joint Offset	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
51.7		Surface Damage	No	2 /		
						
59.9		Joint Offset	No	/		
						
60.0		chip	No	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
60.0		Joint - Gasket	No	12 /		
						
68.0		Joint Offset	No	/		
						
76.2		Joint Offset	No	/		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	84.5	Joint Offset	No	/		
	92.3	Joint Offset	No	/		
	100.3	Joint Offset	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
108.4		Joint Offset	No	/		
						
108.4		Crack	No	7 /		
						
108.4		Crack -Multidirectional	No	3 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	116.7	joint	No	/		
	124.5	Joint Offset	No	/		
	132.5	Joint Offset	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
140.6		Joint Offset	No	/		
						
140.6		Crack	No	12 /		
						
148.5		Joint -Misaligned	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
156.6		joint	No	/		
						
156.6		Broken	No	8 /		
						
156.6		Crack	No	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
164.8		joint	No	/		
						
164.8		Crack	No	5 /		
						
172.6		Joint-Misaligned	No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
172.7		Crack	No	12 /		
						
181.7		End of Pipe	No	/		
						
181.7		STOP	No	/		

**EP-1841**

# Main Inspection with Pipe-Run Graph

Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1841</b>		City: <b>ROCK HILL, SC</b>		Address: <b>PARAGON WAY</b>	
Start date/time: <b>1/9/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>59.5</b>		Operator: <b>Adam Knight</b>		Comments:	



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1841</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>59.5</b>	Operator: <b>Adam Knight</b>	Comments

Asset length: 59.4  
 Surveyed length: 5.1



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP1841	Project Name: York County	Start date/time: 1/9/2020 11:59:00 AM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: EXCB1809	Depth US:	Downstream node: EXCB1810	Depth DS:	Asset length: 59.5	Extra:
----------------------------	-----------	------------------------------	-----------	-----------------------	--------


Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
----------	--------	------	----------	------------	----------	---------

1.0	START WITH FLOW	No	/		
-----	-----------------	----	---	--	--



1.0	joint	No	/		
-----	-------	----	---	--	--



1.0	Crack	No	3 /		
-----	-------	----	-----	--	--

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	7.4	joint	No	/		
	15.2	joint	No	/		
	15.2	Root-in-Joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
23.2	joint		No	/		
23.3	Root-in-Joint		No	5 /		
31.6	Joint Offset		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
33.0		Surface Damage	No	8 /		
39.6		Joint Offset	No	/		
47.4		Joint Offset	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
49.5	10.0	Crack -Major	No	1 /		
						
55.5	joint		No	/		
						
59.5	Abandoned Survey		No	/		TOO DEEP IN WATER


## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
59.5		STOP	No	/		

**EP-1843**

## Main Inspection with Pipe-Run Graph

Project Name: <b>York County</b>		Mainline ID: <b>Y-EP1843</b>		City: <b>ROCK HILL</b>		Address: <b>PARAGON WAY</b>	
Start date/time: <b>1/9/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>70.8</b>		Operator: <b>Adam Knight</b>		Comments	



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP1843	Project Name: York County	Start date/time: 1/9/2020 1:33:29 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: EXCB1811	Depth US:	Downstream node: EXCB1812	Depth DS:	Asset length: 70.8	Extra:
----------------------------	-----------	------------------------------	-----------	-----------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
7.5		joint	Yes	/		
						
7.5		Crack- Circumferenti al	Yes	9 / 6		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	15.4	Joint Offset	Yes	/		
	23.4	Joint Offset	Yes	/		
	31.6	joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	39.6	joint	Yes	/	/	/
	47.6	joint	Yes	/	/	/
	55.8	joint	Yes	/	/	/


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	63.8	joint	Yes	/	/	/
	70.8	End of Pipe	Yes	/	/	/
	70.8	STOP	Yes	/	/	/


**EP-1844**

## Main Inspection with Pipe-Run Graph

Project Name: York County	Mainline ID: Y-EP1844	City: ROCK HILL, SC	Address: PARAGON WAY
Start date/time: 1/9/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: Downstream	Surveyed footage: 118.0	Operator: Adam Knight	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP1844</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>118.0</b>	Operator: <b>Adam Knight</b>	Comments:



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

# Observation Report with Still Images

Mainline ID: Y-EP1844	Project Name: York County	Start date/time: 1/9/2020 1:47:57 PM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXCB1812	Depth US:	Downstream node: EXCB3001	Depth DS:	Asset length: 118.0	Extra:



Comments

---


## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
6.2	joint		No	/		
						
14.0	Joint Offset		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	21.6	Crack	No	11 / 9		
	22.1	joint	No	/		
	30.2	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
38.1	joint		No	/		
						
46.5	joint		No	/		
						
54.3	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	62.5	joint	No	/		
	70.1	joint	No	/		
	78.1	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
86.1	joint		No	/		
						
94.5	joint		No	/		
						
102.7	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	110.5	joint	No	/		
	110.5	Joint - Gasket	No	12 /		
	118.0	End of Pipe	No	/		

AET Services  
623 Rices Creek Road  
Liberty, SC 29657  
1-844-8TOPGUN  
www.aettopgun.com


## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
118.0	STOP	No	/			

**EP-1845.1**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1845.1</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 12:39 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-1845.1**

Start date/time:  
**1/15/2020 12:39 PM**

Direction:  
**With the flow**

Weather:

**Dry**




## Main Inspections Small Photos

Mainline ID: <b>EP-1845.1</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 12:39 PM</b>	Asset length: <b>113.9 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-1813</b>	Depth US:	Downstream node: <b>EX-CB-2410</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
7.6 ft.	D		/	Joint Offset			



15.9 ft.	D		/	Joint Offset			
----------	---	--	---	--------------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

23.8 ft. D / Joint Offset Misaligned



32.0 ft. D / Joint



40.2 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

48.5 ft. D / Joint



56.5 ft. D / Joint Offset



64.8 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

72.7 ft. D / Joint Offset



81.0 ft. D / Joint



89.0 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

97.2 ft. D / Joint




105.3 ft. D / Joint



113.9 ft. D / End of Pipe




## Inspection's photos



**EP-1846**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1846</b>	<b>Rock Hill</b>	
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 10:37 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1846**

Start date/time:  
**1/15/2020 10:37 AM**

Direction:  
**Against the flow**

Weather:  
**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1846</b>	City: <b>Rock Hill</b>	Address:	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 10:37 AM</b>	Asset length: <b>115.1 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-1814</b>	Depth US:	Downstream node: <b>EX-CB-1813</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
5.7 ft.	U		/	Joint			



13.8 ft.	U		/	Joint Offset			
----------	---	--	---	--------------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------


21.7 ft. U / Joint



21.7 ft. U 7 / Broken



29.8 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

38.1 ft. U / Joint



46.1 ft. U / Joint Offset



54.2 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

62.4 ft. U / Joint Offset



70.8 ft. U / Joint Offset



78.6 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

78.7 ft. U 7 / 8 Broken



86.8 ft. U / Joint



94.9 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

103.1 ft. U / Joint Offset




111.2 ft. U / Joint Offset



115.1 ft. U / End of Pipe




## Inspection's photos



**EP-1847**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1847</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 11:01 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1847**

Start date/time:  
**1/15/2020 11:01 AM**

Direction:  
**Against the flow**

Weather:  
**Dry**



## Main Inspections Small Photos


Mainline ID: <b>EP-1847</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 11:01 AM</b>	Asset length: <b>119.2 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-1815</b>	Depth US:	Downstream node: <b>EX-CB-1814</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
4.6 ft.	U		/ Joint Offset			




12.8 ft.	U		/ Joint Offset			
----------	---	--	----------------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

20.8 ft. U / Joint Offset



29.1 ft. U / Joint Offset




37.2 ft. U / Joint Offset




# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

45.5 ft. U / Joint Offset



53.4 ft. U / Joint Offset



61.6 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

69.8 ft. U / Joint Offset



77.9 ft. U / Joint Offset



77.9 ft. U 1 / Broken

Chip



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


86.0 ft. U / Joint Offset



94.2 ft. U / Joint




102.4 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

110.4 ft. U / Joint Offset



110.9 ft. U 9 / Crack



119.2 ft. U / End of Pipe




## Inspection's photos



**EP-1848**


## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1848</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 11:23 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1848</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 11:23 AM</b>	Asset length: <b>109.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-1816</b>	Depth US:	Downstream node: <b>EX-CB-1815</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

## Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
5.4 ft.	U		/	Debris			



7.9 ft.	U		/	Joint			
---------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

16.0 ft. U / Joint Offset



16.0 ft. U / Joint - Gasket



24.1 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

24.1 ft. U 2 / 4 Joint - Gasket



32.3 ft. U / Joint Offset



40.4 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

40.4 ft. U 3 / Crack



43.3 ft. U 6 / Debris



48.6 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

56.8 ft. U / Joint Offset



65.0 ft. U / Joint Offset



73.2 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

81.3 ft. U / Joint Offset



86.3 ft. U 6 / Debris



89.4 ft. U / Joint Offset

**MISALIGNED**



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

97.5 ft. U / Joint Offset




105.6 ft. U / Joint Offset



109.8 ft. U / End of Pipe




## Inspection's photos



**EP-1849**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1849</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 11:50 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1849**

Start date/time:  
**1/15/2020 11:50 AM**

Direction:  
**Against the flow**

Weather:  
**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1849</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 11:50 AM</b>	Asset length: <b>110.1 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-1817</b>	Depth US:	Downstream node: <b>EX-CB-1816</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
8.0 ft.	U		/	Joint			



16.3 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

17.2 ft. U 6 / Debris



24.2 ft. U / Joint Offset




32.5 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

32.5 ft. U 1 / Crack



40.7 ft. U / Joint Offset




48.8 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

57.0 ft. U / Joint Offset



65.5 ft. U / Joint Offset



73.3 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

73.3 ft. U 2 / Crack



74.0 ft. U 10 / Crack



75.0 ft. U 3 / Crack



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

81.3 ft. U / Joint Offset



89.6 ft. U / Joint Offset



98.1 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


105.8 ft. U / Joint



110.1 ft. U / End of Pipe




## Inspection's photos



**EP-1850**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1850</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 10:40 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1850**

Start date/time:  
**1/16/2020 10:40 AM**

Direction:  
**Against the flow**

Weather:  
**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1850</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 10:40 AM</b>	Asset length: <b>113.2 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXDI-34</b>	Depth US:	Downstream node: <b>EXCB-1820</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.6 ft.	U		/	Joint			



14.7 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

22.8 ft. U / Joint Offset



22.8 ft. U 9 / Crack



31.1 ft. U / Joint Offset



# Observations

Distance	Dir. Length	From/To Code	Modifier/Severity	Rating	Comments
----------	-------------	--------------	-------------------	--------	----------

31.1 ft.    U                      9 /    Crack



39.2 ft.    U                      /    Joint



Distance: 39.2 ft.  
Joint -  
Clock from:  
Clock to:  
Rating:

39.2 ft.    U                      11 /    Broken



Distance: 39.2 ft.  
Broken -  
Clock from: 11 @ clock  
Clock to:  
Rating:  
Chip

Chip

# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

47.3 ft. U / Joint



55.6 ft. U / Joint




63.6 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

71.9 ft. U / Joint Offset Misaligned



79.9 ft. U / Joint Offset Misaligned




88.1 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

96.1 ft. U / Joint Offset Misaligned



104.4 ft. U / Joint Offset



113.2 ft. U / End of Pipe




## Inspection's photos



**EP-1851**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1851</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 11:11 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Concrete</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-1851**

Start date/time:  
**1/16/2020 11:11 AM**

Direction:  
**Against the flow**

Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1851</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 11:11 AM</b>	Asset length: <b>112.7 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1819</b>	Depth US:	Downstream node: <b>EXCB-1820</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.6 ft.	U		/	Joint			



14.8 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

22.9 ft. U / Joint



23.0 ft. U / Joint - Gasket



30.9 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

39.1 ft. U / Joint



47.3 ft. U / Joint



47.4 ft. U 9 / Broken



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

55.1 ft. U / Joint Offset



63.3 ft. U / Joint Offset



71.5 ft. U / Joint Offset




# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

71.9 ft. U 6 / 9 Crack



79.6 ft. U / Joint Offset



87.9 ft. U / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

96.0 ft. U / Joint Offset




104.1 ft. U / Joint Offset



112.7 ft. U / End of Pipe




## Inspection's photos



**EP-1852**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1852</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 11:29 AM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Concrete</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-1852**

Start date/time:  
**1/16/2020 11:29 AM**

Direction:  
**With the flow**

Weather:

**Dry**




Project name:  
**York County**

Mainline ID:  
**EP-1852**

Start date/time:  
**1/16/2020 11:29 AM**

Direction:  
**With the flow**

Weather:  
**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1852</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 11:29 AM</b>	Asset length: <b>126.6 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1819</b>	Depth US:	Downstream node: <b>EXCB-1818</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
7.9 ft.	D		/	Joint			



15.8 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

23.9 ft. D / Joint



32.0 ft. D / Joint Offset



40.1 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

48.3 ft. D / Joint Offset



56.6 ft. D / Joint Offset



56.6 ft. D 1 / 2 Broken


Chip



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

64.6 ft. D / Joint Offset



64.6 ft. D / Joint - Gasket



64.6 ft. D 4 / Broken



Chip

# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

64.6 ft. D 12 / Crack



72.5 ft. D / Joint Offset



72.6 ft. D / Joint - Gasket



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

72.6 ft. D 11 / Crack



72.6 ft. D 2 / Crack




72.6 ft. D / Broken



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

72.9 ft. D 7 / Crack



78.8 ft. D 5 / Crack



80.9 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

80.9 ft. D 11 / Crack



89.0 ft. D / Joint Offset




# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

89.0 ft. D 3 / Broken Chip



89.4 ft. D 9 / Crack



97.2 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

105.4 ft. D / Joint Offset



113.4 ft. D / Joint Offset



113.5 ft. D 2 / Joint - Gasket



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

113.5 ft. D 3 / Broken




121.7 ft. D / Joint Offset



126.6 ft. D / End of Pipe




## Inspection's photos



**EP-1852.1**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-1852.1</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 1:38 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>18.0 in.</b>	<b>18.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-1852.1**

Start date/time:  
**1/16/2020 1:38 PM**

Direction:  
**With the flow**

Weather:  
**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-1852.1</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 1:38 PM</b>	Asset length: <b>138.4 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1821</b>	Depth US:	Downstream node: <b>EXMH-1852</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>18.0 in.</b>	Pipe width: <b>18.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
8.1 ft.	D		/	Joint			



15.8 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

15.8 ft. D 3 / Crack



24.2 ft. D / Joint



32.1 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

40.4 ft. D / Joint



48.6 ft. D / Joint Offset




56.7 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

64.7 ft. D / Joint Offset



72.8 ft. D / Joint



72.8 ft. D 3 / Crack



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


80.9 ft. D / Joint Offset



89.1 ft. D / Joint Offset



97.0 ft. D / Joint Offset



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


105.3 ft. D / Joint Offset



111.7 ft. D 6 / Debris



113.5 ft. D / Joint Offset




# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

121.6 ft. D / Joint Offset



129.6 ft. D / Joint Offset



138.4 ft. D / End of Pipe



## Inspection's photos




**EP-2401.2**

## Main Inspection with Pipe-Run Graph and Images

Project Name: <b>York County</b>		Mainline ID: <b>EP2402</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>97.7</b>		Operator: <b>Alex Barlet</b>		Comments	

Surveyed length: 97

**EXDI#13**



0.0ft

**OP2402**

At 2.5 ft  
 START WITH FLOW - Start Inspection With the Flow  
 Category: Miscellaneous

1.0ft



2.0ft

3.0ft

At 4.5 ft  
 joint  
 Category: Structural

4.0ft



5.0ft


6.0ft

7.0ft


8.0ft

9.0ft


Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Weather: <b>Light Rain</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP2402	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 24	Pipe height: 24	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Light Rain
Direction: Downstream	Surveyed footage: 97.7	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2402</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Light Rain</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>97.7</b>	Operator: <b>Alex Barlet</b>	Comments




**Y18.1**

## Main Inspection with Pipe-Run Graph


Project Name: <b>York County</b>		Mainline ID: <b>Y18.1</b>		City: <b>Rock Hill, SC</b>		Address: <b>I77NB right shoulder</b>	
Start date/time: <b>1/8/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>122.3</b>		Operator: <b>Adam Knight</b>		Comments:	



Project Name: <b>York County</b>	Mainline ID: <b>Y18.1</b>	City: <b>Rock Hill, SC</b>	Address: <b>I77NB right shoulder</b>
Start date/time: <b>1/8/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>122.3</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y18.1</b>	City: <b>Rock Hill, SC</b>	Address: <b>I77NB right shoulder</b>
Start date/time: <b>1/8/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>122.3</b>	Operator: <b>Adam Knight</b>	Comments:



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y18.1	Project Name: York County	Start date/time: 1/8/2020 1:50:06 PM	Weather: Dry	Operator: Adam Knight
-----------------------	------------------------------	--	-----------------	--------------------------

Upstream node: Y18.1UP	Depth US:	Downstream node: Y18.1DOWN	Depth DS:	Asset length: 122.3	Extra:
---------------------------	-----------	-------------------------------	-----------	------------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
----------	--------	------	----------	------------	----------	---------

2.0		START AGAINST FLOW	Yes	/		
-----	--	--------------------	-----	---	--	--



6.1		joint	Yes	/		
-----	--	-------	-----	---	--	--



6.2		Joint - Gasket	Yes	2 / 12		
-----	--	----------------	-----	--------	--	--

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
14.3		Joint - Gasket	Yes	12 /		
						
17.2		Crack- Circumferenti al	Yes	12 / 12		
						
22.1		Joint Offset	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
30.1	joint		Yes	/		
						
30.1	chip		Yes	/		
						
38.1	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
38.1	chip		Yes	4 /		
						
46.3	joint		Yes	/		
						
46.3	chip		Yes	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
54.6	joint		Yes	/		
						
54.6	chip		Yes	/		
						
59.7	16.9	Crack	Yes	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
			62.5	joint	Yes	/
		70.3	joint	Yes	/	
		78.5	joint	Yes	/	


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
78.5		Aggregate showing	Yes	12 / 12		at the joint
						
86.6		Joint Offset	Yes	/		j
						
86.6		Joint - Gasket	Yes	12 / 12		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
		Joint Offset	Yes	/		
		Joint - Gasket	Yes	/		
		Broken	Yes	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
94.4		Crack	Yes	10 /		
						
102.4		Joint Offset	Yes	/		
						
						
102.4		chip	Yes	/		

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
110.5		Joint Offset	Yes	/		
						
118.9		Joint Offset	Yes	/		
						
118.9	chip		Yes	9 /		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
118.9	2.3	Crack	Yes	12 /		
						
122.3		End of Pipe	Yes	/		
						
122.3		STOP	Yes	/		


**EP-1814**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP1814</b>		City: <b>York, SC</b>		Address: <b>177 NB`</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>186.1</b>		Operator: <b>Alex Barlet</b>		Comments	



Project Name: York County	Mainline ID: EP1814	City: York, SC	Address: 177 NB`
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 186.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1814	City: York, SC	Address: 177 NB`
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 186.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>177 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>177 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP1814	City: York, SC	Address: 177 NB`
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 186.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1814	City: York, SC	Address: 177 NB`
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 186.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1814	City: York, SC	Address: 177 NB`
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 186.1	Operator: Alex Barlet	Comments



Project Name: York County	Mainline ID: EP1814	City: York, SC	Address: 177 NB`
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: UPSTREAM	Surveyed footage: 186.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP1814	City: York, SC	Address: 177 NB`
Start date/time: 1/27/2020	Pipe width: 18	Pipe height: 18	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Dry
Direction: UPSTREAM	Surveyed footage: 186.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>177 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>177 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>177 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>177 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>177 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP1814</b>	City: <b>York, SC</b>	Address: <b>I77 NB`</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>18</b>	Pipe height: <b>18</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>186.1</b>	Operator: <b>Alex Barlet</b>	Comments




**EP-2401**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP2401</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>		Surveyed footage: <b>88.0</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP2401	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 24	Pipe height: 24	Pipe type: Concrete Reinforced
		Surface condition: Asphalt	Weather: Light Rain
Direction: UPSTREAM	Surveyed footage: 88.0	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>
Direction: <b>UPSTREAM</b>	Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP2401</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>UPSTREAM</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Light Rain</b>	Comments:
Surveyed footage: <b>88.0</b>	Operator: <b>Alex Barlet</b>	Comments:	



**EP-2402**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2402</b>	<b>Rock Hill</b>	<b>Celriver Rd</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 9:14 AM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>



## Main Inspections Small Photos

Mainline ID: <b>EP-2402</b>	City: <b>Rock Hill</b>	Address: <b>Celriver Rd</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 9:14 AM</b>	Asset length: <b>54.3 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-2402</b>	Depth US:	Downstream node: <b>EXCB-2401</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
5.0 ft.	D		/	Joint			



13.1 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--




# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

21.2 ft. D / Joint



29.3 ft. D / Joint Offset



37.4 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

37.4 ft. D / Joint - Gasket




45.6 ft. D / Joint Offset



54.3 ft. D / End of Pipe




## Inspection's photos



**EP-2403**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2403</b>	<b>Rock Hill</b>	<b>Celriver Rd</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 8:58 AM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Asphalt</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>



## Main Inspections Small Photos

Mainline ID: <b>EP-2403</b>	City: <b>Rock Hill</b>	Address: <b>Celriver Rd</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 8:58 AM</b>	Asset length: <b>31.2 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-2403</b>	Depth US:	Downstream node: <b>EXCB-2402</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.0 ft.	D		/	Joint			




14.4 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations


Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

22.7 ft. D / Joint - Gasket



22.7 ft. D / Broken


Chip



31.2 ft. D / End of Pipe




## Inspection's photos



**EP-2404**

## Main Inspections Pipe Run

Project name: <b>York County</b>	Mainline ID: <b>EP-2404</b>	City: <b>Rock Hill</b>	Address: <b>Celriver Rd</b>
Start date/time: <b>1/16/2020 9:25 AM</b>	Direction: <b>With the flow</b>	Weather: <b>Dry</b>	Surface condition: <b>Other</b>
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>



## Main Inspections Small Photos

Mainline ID: <b>EP-2404</b>	City: <b>Rock Hill</b>	Address: <b>Celriver Rd</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 9:25 AM</b>	Asset length: <b>25.2 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-2401</b>	Depth US:	Downstream node: <b>OP-2403</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
8.6 ft.	D		/	Joint			



16.6 ft.	D		/	Joint Offset			
----------	---	--	---	--------------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

25.2 ft. D / End of Pipe




## Inspection's photos



**EP-2405**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2405</b>	<b>Rock Hill</b>	<b>Celriver Rd</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 9:38 AM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>




Project name:  
**York County**

Mainline ID:  
**EP-2405**

Start date/time:  
**1/16/2020 9:38 AM**

Direction:  
**Against the flow**

Weather:  
**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-2405</b>	City: <b>Rock Hill</b>	Address: <b>Celriver Rd</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 9:38 AM</b>	Asset length: <b>128.5 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-2404</b>	Depth US:	Downstream node: <b>EXCB-2403</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

## Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.4 ft.	U		/	Joint			



14.3 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

22.6 ft. U / Joint



30.7 ft. U / Joint



38.9 ft. U / Joint




# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

47.0 ft. U / Joint



47.0 ft. U 4 / 6 Broken



55.2 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

63.1 ft. U / Joint



71.4 ft. U / Joint



79.5 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

87.4 ft. U / Joint



95.6 ft. U / Joint



103.9 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

111.9 ft. U / Joint



120.1 ft. U / Joint



128.5 ft. U / End of Pipe




## Inspection's photos




**EP-2407**

## Main Inspection with Pipe-Run Graph


Project Name: York County	Mainline ID: Y-EP2407	City: ROCK HILL, SC	Address: PARAGON WAY
Start date/time: 1/9/2020	Pipe width: 24	Pipe height: 24	Pipe type: Concrete Reinforced
		Surface condition: Sidewalk	Weather: Dry
Direction: Downstream	Surveyed footage: 243.8	Operator: Adam Knight	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP2407</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>243.8</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP2407</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>243.8</b>	Operator: <b>Adam Knight</b>	Surface condition: <b>Sidewalk</b>
			Weather: <b>Dry</b>
Comments			



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP2407	Project Name: York County	Start date/time: 1/9/2020 3:20:57 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: EXCB2406	Depth US:	Downstream node: EXCB2405	Depth DS:	Asset length: 243.8	Extra:
----------------------------	-----------	------------------------------	-----------	------------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
3.6		Joint Offset	No	/		
						
11.8		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	19.9	joint	No	/		
	27.9	Joint Offset	No	/		
	36.0	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
36.0	chip		No	2 /		
						
44.0	joint		No	/		
						
52.0	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
60.0	joint		No	/		
						
68.3	joint		No	/		
						
76.3	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
84.3	joint		No	/		
						
92.6	joint		No	/		
						
100.5	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
108.4		joint	No	/		
						
108.4		Crack	No	12 /		
						
116.5		Joint Offset	No	/		

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
116.5	Crack		No	6 /		
						
116.5	Root-in-Joint		No	6 /		
						
124.8	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
132.9	joint		No	/		
						
140.9	joint		No	/		
						
149.0	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	156.9	joint	No	/		
	165.2	joint	No	/		
	173.4	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
173.4	Crack		No	8 /		
						
173.5	Crack		No	3 /		
						
181.1	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	189.4	joint	No	/		
	197.5	Joint Offset	No	/		
	205.6	Joint Offset	No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
213.3	joint		No	/		
						
213.3	chip		No	5 /		
						
221.6	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
229.7	joint		No	/		
						
237.8	joint		No	/		
						
237.8	Crack		No	10 /		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
243.8		End of Pipe	No	/		
						
243.8		STOP	No	/		


**EP-2408**

## Main Inspection with Pipe-Run Graph

Project Name: <b>York County</b>		Mainline ID: <b>Y-EP2408</b>		City: <b>ROCK HILL, SC</b>		Address: <b>PARAGON WAY</b>	
Start date/time: <b>1/9/2020</b>		Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Sidewalk</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>115.1</b>		Operator: <b>Adam Knight</b>		Comments:	



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP2408</b>	City: <b>ROCK HILL, SC</b>	Address: <b>PARAGON WAY</b>
Start date/time: <b>1/9/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Sidewalk</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>115.1</b>	Operator: <b>Adam Knight</b>	Comments:



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP2408	Project Name: York County	Start date/time: 1/9/2020 2:53:31 PM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXMH2401	Depth US:	Downstream node: EXCB2406	Depth DS:	Asset length: 115.1	Extra:

Comments

---



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.0		START WITH FLOW	No	/		
						
2.0	joint		No	/		
						
9.5	joint		No	/		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
17.7	joint		No	/		
						
17.7	Crack		No	12 /		
						
17.7	Crack		No	11 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
25.6	joint		No	/		
						
33.8	joint		No	/		
						
41.8	joint		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
49.9	joint		No	/		
						
49.9	Crack		No	12 /		
						
58.0	joint		No	/		
						


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	65.9	joint	No	/		
	74.4	joint	No	/		
	82.2	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
90.3	joint		No	/		
						
98.4	Joint Offset		No	/		
						
106.4	Joint Offset		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
115.1		End of Pipe	No	/		
						
115.1		STOP	No	/		

**EP-2409**

## Main Inspection with Pipe-Run Graph

Project Name: <b>York County</b>		Mainline ID: <b>Y-EP2409</b>		City: <b>ROCK HILL, SC</b>		Address: <b>PARAGON WAY</b>	
Start date/time: <b>1/9/2020</b>		Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>18.1</b>		Operator: <b>Adam Knight</b>		Comments:	



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP2409	Project Name: York County	Start date/time: 1/9/2020 2:47:26 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: EXCB2407	Depth US:	Downstream node: EXMH2401	Depth DS:	Asset length: 18.1	Extra:
----------------------------	-----------	------------------------------	-----------	-----------------------	--------


Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
----------	--------	------	----------	------------	----------	---------

2.0	START WITH FLOW	No	/		
-----	-----------------	----	---	--	--



2.0	joint	No	/		
-----	-------	----	---	--	--



9.8	joint	No	/		
-----	-------	----	---	--	--


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
18.1		End of Pipe	No	/		
						
18.1		STOP	No	/		

**EP-2410**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2410</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 1:41 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-2410**

Start date/time:  
**1/15/2020 1:41 PM**

Direction:  
**With the flow**

Weather:

**Dry**




## Main Inspections Small Photos

Mainline ID: <b>EP-2410</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 1:41 PM</b>	Asset length: <b>92.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-2408</b>	Depth US:	Downstream node: <b>EX-CB-2407</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
3.0 ft.	D		/	Joint			



11.3 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

19.4 ft. D / Joint




27.5 ft. D / Joint



35.7 ft. D / Joint Offset

Misaligned



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

43.7 ft. D / Joint



51.8 ft. D / Joint



59.9 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

67.9 ft. D / Joint



76.3 ft. D / Joint



84.6 ft. D / Joint Offset



# Observations

Distance	Dir. Length	From/To Code	Modifier/Severity	Rating	Comments
----------	-------------	--------------	-------------------	--------	----------

92.8 ft. D / End of Pipe




## Inspection's photos



**EP-2411**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2411</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 1:24 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-2411**

Start date/time:  
**1/15/2020 1:24 PM**

Direction:  
**With the flow**

Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-2411</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 1:24 PM</b>	Asset length: <b>114.3 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-2409</b>	Depth US:	Downstream node: <b>EX-CB-2408</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

## Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
7.9 ft.	D		/	Joint			




16.1 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

24.0 ft. D / Joint Offset



32.2 ft. D / Joint Offset

Misaligned



40.5 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

48.8 ft. D / Joint



56.9 ft. D / Joint



65.1 ft. D / Joint Offset


Misaligned



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

73.1 ft. D / Joint Offset



81.4 ft. D / Joint



89.5 ft. D / Joint Offset

Misaligned



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

97.8 ft. D / Joint



105.7 ft. D / Joint Offset

Misaligned



114.3 ft. D / End of Pipe




## Inspection's photos



**EP-2412**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2412</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/15/2020 1:01 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>



Project name:  
**York County**


Mainline ID:  
**EP-2412**

Start date/time:  
**1/15/2020 1:01 PM**

Direction:  
**With the flow**

Weather:

**Dry**



## Main Inspections Small Photos

Mainline ID: <b>EP-2412</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/15/2020 1:01 PM</b>	Asset length: <b>123.9 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EX-CB-2410</b>	Depth US:	Downstream node: <b>EX-CB-2409</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

## Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
9.0 ft.	D		/	Joint			



17.4 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

25.6 ft. D / Joint Offset



33.7 ft. D / Joint



41.8 ft. D / Joint Offset

Misaligned



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

41.8 ft. D 2 / Crack



50.0 ft. D / Joint



58.0 ft. D / Joint Offset

Misaligned



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

66.3 ft. D / Joint



74.4 ft. D / Joint Offset

Misaligned



82.7 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

90.7 ft. D / Joint



98.8 ft. D / Joint Offset



107.2 ft. D / Joint Offset



## Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

115.3 ft. D / Joint



123.9 ft. D / End of Pipe




## Inspection's photos



**EP-2413**

## Main Inspection with Pipe-Run Graph

Project Name: <b>York County</b>		Mainline ID: <b>Y-EP2413</b>		City: <b>ROCK HILL</b>		Address: <b>PARAGON WAY</b>	
Start date/time: <b>1/9/2020</b>	Pipe width: <b>24</b>	Pipe height: <b>24</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>		
Direction: <b>Downstream</b>	Surveyed footage: <b>55.3</b>	Operator: <b>Adam Knight</b>		Comments			



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP2413	Project Name: York County	Start date/time: 1/9/2020 4:04:31 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: EXCB2405	Depth US:	Downstream node: EXMH2402	Depth DS:	Asset length: 55.3	Extra:
----------------------------	-----------	------------------------------	-----------	-----------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
6.7		joint	No	/		
						
6.7		Crack	No	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	14.9	joint	No	/		
	22.9	joint	No	/		
	30.8	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
30.8		Crack	No	12 /		
						
						
38.8		Joint -Misaligned	No	/		
						
47.1		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
55.3		End of Pipe	No	/		
						
55.3		STOP	No	/		

**EP-2414**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images


Mainline ID: Y-EP2414	Project Name: York County	Start date/time: 1/16/2020 10:26:50 AM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: OP2404	Depth US:	Downstream node: EXCB2411	Depth DS:	Asset length: 47.9	Extra:
--------------------------	-----------	------------------------------	-----------	-----------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
3.8		joint	Yes	/		
						
4.1		Joint - Gasket	Yes	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
11.9	joint		Yes	/		
						
19.9	joint		Yes	/		
						
19.9	Crack		Yes	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
27.9		joint	Yes	/		
						
28.3	15.7	Crack -Major	Yes	12 /		
						
35.9		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
44.0		joint	Yes	/		
						
44.0		Rebar Exposed	Yes	4 /		
						
47.9		End of Pipe	Yes	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
47.9	STOP	STOP	Yes	/		

**EP-2415**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2415</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 12:25 PM</b>	<b>Against the flow</b>	<b>Dry</b>	<b>Concrete</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>



## Main Inspections Small Photos


Mainline ID: <b>EP-2415</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 12:25 PM</b>	Asset length: <b>65.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-1820</b>	Depth US:	Downstream node: <b>EXCB-2412</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
6.9 ft.	U		/	Joint			



15.0 ft.	U		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

23.5 ft. U / Joint



31.5 ft. U / Joint



39.3 ft. U / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

47.6 ft. U / Joint



47.6 ft. U 6 / 9 Crack



47.6 ft. U 3 / 6 Crack



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

55.8 ft. U / Joint




63.9 ft. U / Joint



65.8 ft. U / End of Pipe




## Inspection's photos



**EP-2416**

## Main Inspections Pipe Run

Project name:	Mainline ID:	City:	Address:
<b>York County</b>	<b>EP-2416</b>	<b>Rock Hill</b>	<b>Paragon Way</b>
Start date/time:	Direction:	Weather:	Surface condition:
<b>1/16/2020 12:42 PM</b>	<b>With the flow</b>	<b>Dry</b>	<b>Other</b>
Pipe shape:	Pipe material:	Pipe height:	Pipe width:
<b>Circular</b>	<b>Concrete Reinforced</b>	<b>24.0 in.</b>	<b>24.0 in.</b>



Project name:  
**York County**

Mainline ID:  
**EP-2416**


Start date/time:  
**1/16/2020 12:42 PM**

Direction:  
**With the flow**

Weather:

**Dry**

Mainline length: 68.8 ft.  
Surveyed length: 68.8 ft.



## Main Inspections Small Photos

Mainline ID: <b>EP-2416</b>	City: <b>Rock Hill</b>	Address: <b>Paragon Way</b>	Project name: <b>York County</b>
Start date/time: <b>1/16/2020 12:42 PM</b>	Asset length: <b>68.8 ft.</b>	Weather: <b>Dry</b>	Operator: <b>Chance</b>
Upstream node: <b>EXCB-2412</b>	Depth US:	Downstream node: <b>OP-2410</b>	Depth DS:
Pipe shape: <b>Circular</b>	Pipe material: <b>Concrete Reinforced</b>	Pipe height: <b>24.0 in.</b>	Pipe width: <b>24.0 in.</b>
Comments:			

### Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
3.5 ft.	D		/	Joint			



11.2 ft.	D		/	Joint			
----------	---	--	---	-------	--	--	--



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------

19.5 ft. D / Joint



27.2 ft. D / Joint



27.3 ft. D 6 / 8 Crack



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

35.7 ft. D / Joint



35.7 ft. D 3 / 9 Crack



43.9 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To	Code	Modifier/Severity	Rating	Comments
----------	------	--------	---------	------	-------------------	--------	----------

51.9 ft. D / Joint



58.9 ft. D / Debris



60.2 ft. D / Joint



# Observations

Distance	Dir.	Length	From/To Code	Modifier/Severity	Rating	Comments
----------	------	--------	--------------	-------------------	--------	----------


68.8 ft. D 6 / Debris



68.8 ft. D / Abandoned Survey



## Inspection's photos



**EP-3001**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP3001	Project Name: York County	Start date/time: 1/16/2020 12:40:23 PM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXMH2402	Depth US:	Downstream node: EXCB3001	Depth DS:	Asset length: 80.3	Extra:
Comments					

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
6.8		joint	No	/		
						
14.7		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	14.7	Crack	No	6 /		
	14.7	Joint - Gasket	No	12 /		
	22.7	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	22.7	24.3	Crack -Major	No	6 /	
	30.7		Joint - Gasket	No	/	
	30.7	24.6	Crack -Major	No	12 /	


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
38.9	joint		No	/		
						
38.9	Crack-Circumferenti al		No	7 / 4		
						
47.0	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
47.0		Joint - Gasket	No	1 /		
						
55.3		joint	No	/		
						
63.0		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
63.0		Crack -Multidirectional	No	3 / 6		
						
65.4	4.9	Crack -Major	No	5 /		
						
71.2		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	71.2	chip	No	3 /		
	80.3	End of Pipe	No	/		
	80.3	STOP	No	/		

**EP-3002**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP3002	Project Name: York County	Start date/time: 1/16/2020 1:13:42 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: EXCB3001	Depth US:	Downstream node: OP3002	Depth DS:	Asset length: 85.9	Extra:
----------------------------	-----------	----------------------------	-----------	-----------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
5.8		joint	No	/		
						
13.3		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
21.5		joint	No	/		
						
29.2		Joint Offset	No	/		
						
29.2	8.1	Crack -Major	No	6 /		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
37.3	joint		No	/		
						
45.4	Joint Offset		No	/		
						
53.6	Joint Offset		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	61.4	joint	No	/		
	69.9	Joint Offset	No	/		
	77.6	Joint Offset	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
77.6	8.3	Crack -Major	No	12 /		
						
85.9		End of Pipe	No	/		
						
86.3		STOP	No	/		

**EP-3600**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images



Mainline ID: Y-EP3600	Project Name: York County	Start date/time: 1/16/2020 3:01:44 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: OP3601	Depth US:	Downstream node: EXDI#31	Depth DS:	Asset length: 98.1	Extra:
--------------------------	-----------	-----------------------------	-----------	-----------------------	--------



Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.0		joint	No	/		
						
2.0	96.1	Crack -Major	No	12 /		MULTIPLE
						
2.5		START WITH FLOW	No	/		

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
5.3	joint		No	/		
						
8.6	joint		No	/		
						
12.9	joint		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	16.9	joint	No	/		
	21.2	joint	No	/		
	25.4	joint	No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	29.0	joint	No	/		
	33.3	joint	No	/		
	37.8	joint	No	/		




### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
41.5	joint		No	/		
						
46.1	chip		No	9 /		
						
49.5	joint		No	/		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
53.8	joint		No	/		
						
58.4	joint		No	/		
						
62.1	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
66.3	joint		No	/		
						
70.2	joint		No	/		
						
71.7	Crack -Multidirectional		No	9 /		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	73.2	Crack	No	3 /		
	74.5	joint	No	/		
	78.3	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
82.3	joint		No	/		
						
86.5	joint		No	/		
						
90.6	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
94.7	joint		No	/		
						
94.7	Broken		No	5 /		
						
98.1	End of Pipe		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
98.1	STOP	No	/			


**EP-3601**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP3600</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>96.1</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments:
Surveyed footage: 96.1	Operator: Alex Barlet		




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>		




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments
Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>		



Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments



**EP-3602**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images


Mainline ID: Y-EP3602	Project Name: York County	Start date/time: 1/16/2020 2:10:05 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: OP3604	Depth US:	Downstream node: OP3605	Depth DS:	Asset length: 58.1	Extra:
--------------------------	-----------	----------------------------	-----------	-----------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
5.1	joint		Yes	/		
						
5.1	53.0	Crack -Major	Yes	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	13.1	joint	Yes	/		
	13.1	chip	Yes	11 /		
	17.4	joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
25.5		joint	Yes	/		
						
28.7		Crack-Circumferential	Yes	2 /		MULTIPLE
						
33.7		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
35.9		Crack-Circumferential	Yes	4 /		
						
41.4	joint		Yes	/		
						
41.5	16.6	Crack -Major	Yes	1 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
50.0	joint		Yes	/		
						
58.1	End of Pipe		Yes	/		
						
58.2	STOP		Yes	/		

**EP-3603**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP3603	Project Name: York County	Start date/time: 1/16/2020 10:13:04 AM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: EXCB2411	Depth US:	Downstream node: OP3603	Depth DS:	Asset length: 36.4	Extra:
----------------------------	-----------	----------------------------	-----------	-----------------------	--------

Comments

---


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
2.9		joint	No	/		
						
9.8		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
17.8	joint		No	/		
						
25.7	joint		No	/		
						
34.0	joint		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
36.3		End of Pipe	No	/		
						
36.4		STOP	No	/		


**EP-42.1**

## Main Inspection with Pipe-Run Graph


Project Name: <b>York County</b>		Mainline ID: <b>Y-EP-42.1</b>		City: <b>Rock Hill, SC</b>		Address: <b>177SB Right shoulder</b>	
Start date/time: <b>1/8/2020</b>		Pipe width: <b>42</b>	Pipe height: <b>42</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>290.8</b>		Operator: <b>Adam Knight</b>		Comments:	




Project Name: <b>York County</b>	Mainline ID: <b>Y-EP-42.1</b>	City: <b>Rock Hill, SC</b>	Address: <b>177SB Right shoulder</b>
Start date/time: <b>1/8/2020</b>	Pipe width: <b>42</b>	Pipe height: <b>42</b>	Pipe type: <b>Concrete Reinforced</b>
		Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>290.8</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP-42.1</b>	City: <b>Rock Hill, SC</b>	Address: <b>177SB Right shoulder</b>
Start date/time: <b>1/8/2020</b>	Pipe width: <b>42</b>	Pipe height: <b>42</b>	Weather: <b>Dry</b>
		Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>290.8</b>	Operator: <b>Adam Knight</b>	Comments:



Project Name: <b>York County</b>	Mainline ID: <b>Y-EP-42.1</b>	City: <b>Rock Hill, SC</b>	Address: <b>177SB Right shoulder</b>
Start date/time: <b>1/8/2020</b>	Pipe width: <b>42</b>	Pipe height: <b>42</b>	Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>290.8</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>
Operator: <b>Adam Knight</b>		Comments:	



AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP-42.1	Project Name: York County	Start date/time: 1/8/2020 3:22:29 PM	Weather: Dry	Operator: Adam Knight
---------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: OP-42.01	Depth US:	Downstream node: OP-42.02	Depth DS:	Asset length: 290.8	Extra:
----------------------------	-----------	------------------------------	-----------	------------------------	--------


Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
----------	--------	------	----------	------------	----------	---------

2.5	START WITH FLOW	No	/		
-----	-----------------	----	---	--	--




4.9	joint	No	/		
-----	-------	----	---	--	--




10.6	joint	No	/		
------	-------	----	---	--	--


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
		10.6	49.5	Crack	No	12 /
		16.6		joint	No	/
		22.6		Grouted	No	/


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
28.6	joint		No	/		
						
35.0	Grouted		No	/		
						
41.1	Grouted		No	/		


## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
47.3	Grouted		No	/		
						
52.7	Grouted		No	/		
						
59.0	Grouted		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
59.0		Rebar Exposed	No	/		
						
64.9		Grouted	No	/		
						
71.2		Grouted	No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
77.3		Grouted	No	/		
						
83.4		Grouted	No	/		
						
89.5		Grouted	No	/		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
89.5		Rebar Exposed	No	/		
						
95.5		Grouted	No	/		
						
101.8		Grouted	No	/		




### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
105.9		Aggregate showing	No	/		
						
107.9		Grouted	No	/		
						
113.6		Grouted	No	/		


## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
119.8		Grouted	No	/		
						
126.2		Grouted	No	/		
						
132.0		Grouted	No	/		

### Observations




Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
135.2		Crack -Multidirectional	No	3 /		
						
138.2		Grouted	No	/		
						
144.1		Grouted	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
150.1		Grouted	No	/		
						
150.2		Crack -Multidirectional	No	/		
						
154.5		Junction Box	No	/		EXDI#14




### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
175.0		Grouted	No	/		
						
181.1		Grouted	No	/		
						
186.9		Grouted	No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
193.3		Grouted	No	/		
						
199.2		Grouted	No	/		
						
205.5		Grouted	No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
211.4		Gouted	No	/		
						
217.8		Gouted	No	/		
						
223.8		Gouted	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
230.0		Grouted	No	/		
						
235.7		Grouted	No	/		
						
242.0		Grouted	No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
248.0		Grouted	No	/		
						
254.1		Grouted	No	/		
						
260.3		Grouted	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
266.2		Grouted	No	/		
						
272.7		Grouted	No	/		
						
278.9		Grouted	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
284.5		Grouted	No	/		
						
290.8		End of Pipe	No	/		
						
290.8		STOP	No	/		

**EP-4803**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images



Mainline ID: Y-EP4803	Project Name: York County	Start date/time: 1/16/2020 11:36:47 AM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: EXCB4802	Depth US:	Downstream node: OP4803	Depth DS:	Asset length: 63.8	Extra:
----------------------------	-----------	----------------------------	-----------	-----------------------	--------


Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
7.9		joint	Yes	/		
						
15.7		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
15.7		Broken	Yes	2 / 5		
						
24.8		joint	Yes	/		
						
24.8	39.0	Crack -Major	Yes	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
31.3	joint		Yes	/		
						
39.8	joint		Yes	/		
						
47.6	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
52.0		Surface Damage	Yes	4 /		
						
55.1		joint	Yes	/		
						
63.8		End of Pipe	Yes	/		

AET Services  
623 Rices Creek Road  
Liberty, SC 29657  
1-844-8TOPGUN  
www.aettopgun.com

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
63.8	STOP	Yes	/			

**EP-4804**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com



## Observation Report with Still Images

Mainline ID: Y-EP4804.	Project Name: York County	Start date/time: 1/15/2020 12:21:44 PM	Weather: Light Rain	Operator: Adam Knight	
Upstream node: EXCB4803	Depth US:	Downstream node: EXCB4804	Depth DS:	Asset length: 133.0	Extra:
Comments					


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
2.5	130.5	Crack -Major	Yes	12 /		
						
7.0		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	7.0	121.3	Crack -Major	Yes	6 /	
	15.1	joint	joint	Yes	/	
	23.2	joint	joint	Yes	/	

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
31.5	joint		Yes	/		
						
39.1	joint		Yes	/		
						
47.3	joint		Yes	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
55.2	joint		Yes	/		
						
63.7	joint		Yes	/		
						
71.9	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	71.9	Crack-Circumferential	Yes	9 / 11		
	79.5	joint	Yes	/		
	87.8	joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
95.6	joint		Yes	/		
						
104.5	joint		Yes	/		
						
111.7	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	120.3	joint	Yes	/		
	128.2	joint	Yes	/		
	133.0	End of Pipe	Yes	/		

AET Services  
623 Rices Creek Road  
Liberty, SC 29657  
1-844-8TOPGUN  
www.aettopgun.com

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
133.0		STOP	Yes	/		


**EP-4805**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP4804	Project Name: York County	Start date/time: 1/15/2020 11:53:37 AM	Weather: Heavy Rain	Operator: Adam Knight	
Upstream node: EXCB4804	Depth US:	Downstream node: EXCB4805	Depth DS:	Asset length: 126.2	Extra:
Comments					

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
5.5		joint	Yes	/		
						
5.5	120.7	Crack -Major	Yes	6 /		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	13.2	joint	Yes	/		
	13.2	88.8	Crack -Major	Yes	12	/
	21.1	joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
29.0	joint		Yes	/		
						
37.1	joint		Yes	/		
						
45.0	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
53.3	joint		Yes	/		
						
61.5	joint		Yes	/		
						
69.2	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
77.8	joint		Yes	/		
						
85.5	joint		Yes	/		
						
93.5	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
102.0		joint	Yes	/		
						
109.8		joint	Yes	/		
						
109.9	16.3	Crack -Major	Yes	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
116.5		Crack- Circumferenti al	Yes	2 / 4		
117.8	joint		Yes	/		
121.2	Surface Damage		Yes	/		

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
126.2		End of Pipe	Yes	/		
						
126.2		STOP	Yes	/		

**EP-4806**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com


## Observation Report with Still Images

Mainline ID: Y-EP4806	Project Name: York County	Start date/time: 1/15/2020 11:03:48 AM	Weather: Light Rain	Operator: Adam Knight	
Upstream node: EXCB4805	Depth US:	Downstream node: EXCB4806	Depth DS:	Asset length: 291.3	Extra:


Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
2.5	5.7	Crack -Major	No	6 /		
						
8.2		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	15.8	joint	No	/		
	23.5	joint	No	/		
	23.6	Joint Offset	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
31.8	joint		No	/		
						
39.7	Joint Offset		No	/		
						
48.0	joint		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
48.1		Crack	No	6 /		
						
55.8		joint	No	/		
						
55.8	8.3	Crack -Major	No	6 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
64.0	joint		No	/		
						
69.1	222.2	Crack	No	6 /		
						
72.4	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
80.2	joint		No	/		
						
88.3	joint		No	/		
						
96.4	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
104.0		joint	No	/		
						
105.9	185.4	Crack -Major	No	12 /		
						
112.6		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
120.4		Joint Offset	No	/		
						
128.6		joint	No	/		
						
132.5		Surface Damage	No	9 / 3		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
136.5	joint		No	/		
						
144.4	joint		No	/		
						
152.8	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
160.6	joint		No	/		
						
168.9	joint		No	/		
						
176.7	joint		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
181.0		Surface Damage	No	10 / 8		
						
184.4		joint	No	/		
						
192.8		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
200.7	joint		No	/		
						
208.8	joint		No	/		
						
216.8	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
224.8	joint		No	/		
						
233.8	joint		No	/		
						
241.3	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
249.5	joint		No	/		
						
257.7	joint		No	/		
						
265.7	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
273.8	joint		No	/		
						
281.8	joint		No	/		
						
291.3	End of Pipe		No	/		

AET Services  
623 Rices Creek Road  
Liberty, SC 29657  
1-844-8TOPGUN  
www.aettopgun.com

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
291.3	STOP	No	/			

**EP-4807**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP4807	Project Name: York County	Start date/time: 1/15/2020 2:39:20 PM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXCB4806	Depth US:	Downstream node: EXMH4801	Depth DS:	Asset length: 324.5	Extra:

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
2.8		joint	No	/		
						
2.8	321.7	Crack -Major	No	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
4.0	320.5	Crack -Major	No	6 /		
						
8.6	joint		No	/		
						
8.6	Joint Offset		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	16.5	Joint Offset	No	/		
	24.9	Joint Offset	No	/		
	33.0	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
41.2	joint		No	/		
						
48.9	Joint Offset		No	/		
						
57.3	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
64.9	joint		No	/		
						
73.4	joint		No	/		
						
81.0	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	89.3	Joint Offset	No	/		
	97.6	joint	No	/		
	105.8	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
113.8	joint		No	/		
						
121.7	joint		No	/		
						
129.8	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
138.0	joint		No	/		
						
146.0	joint		No	/		
						
154.1	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	162.0	joint	No	/		
	170.8	Joint Offset	No	/		
	178.6	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
186.6	joint		No	/		
						
194.6	joint		No	/		
						
203.0	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
210.6	joint		No	/		
						
219.0	joint		No	/		
						
227.2	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
235.3	joint		No	/		
						
242.9	joint		No	/		
						
251.0	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
259.3	joint		No	/		
						
267.7	joint		No	/		
						
275.7	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
283.5	joint		No	/		
						
291.4	joint		No	/		
						
299.6	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
307.7	joint		No	/		
						
316.0	joint		No	/		
						
324.5	End of Pipe		No	/		

AET Services  
623 Rices Creek Road  
Liberty, SC 29657  
1-844-8TOPGUN  
www.aettopgun.com

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
324.5	STOP	No	/			

**EP-4808**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP4808	Project Name: York County	Start date/time: 1/15/2020 3:44:42 PM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXMH4801	Depth US:	Downstream node: EXDI#36	Depth DS:	Asset length: 310.3	Extra:
Comments					

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
2.5	307.8	Crack -Major	No	6 /		
						
7.6		joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
15.4	joint		No	/		
						
23.6	joint		No	/		
						
32.3	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
32.3	278.0	Crack	No	12 /		
						
39.9		joint	No	/		
						
39.9	8.0	Crack -Major	No	9 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
47.9	joint		No	/		
						
55.6	joint		No	/		
						
64.1	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
72.5	joint		No	/		
						
78.7	Infiltration		No	12 /		
						
80.1	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
88.5	joint		No	/		
						
96.5	joint		No	/		
						
104.9	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
112.6	joint		No	/		
						
112.6	Infiltration		No	12 /		
						
120.8	joint		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
128.9	joint		No	/		
						
137.0	joint		No	/		
						
145.2	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
153.7	joint		No	/		
						
161.3	joint		No	/		
						
169.5	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	177.1	joint	No	/		
	185.3	joint	No	/		
	193.4	Grouted	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
201.7	joint		No	/		
						
209.7	joint		No	/		
						
217.6	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
225.9	joint		No	/		
						
233.9	joint		No	/		
						
241.8	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
250.4	joint		No	/		
						
258.0	joint		No	/		
						
265.8	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	joint		No	/		
	joint		No	/		
	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
298.4		joint	No	/		
						
310.3		End of Pipe	No	/		
						
310.3		STOP	No	/		

**EP-4809**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images


Mainline ID: EP4810.	Project Name: York County	Start date/time: 1/16/2020 8:49:41 AM	Weather: Dry	Operator: Adam Knight
-------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: EXDI#37	Depth US:	Downstream node: EXCB4807	Depth DS:	Asset length: 233.5	Extra:
---------------------------	-----------	------------------------------	-----------	------------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
4.6		joint	Yes	/		
						
12.1		joint	Yes	/		
						
20.3		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	21.7	211.7	Crack -Major	Yes	12 /	
	28.1	joint	joint	Yes	/	
	30.8	Hole	Hole	Yes	/	LIFT POINT NOT GROUTED(EVERY JOINT)

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	36.0	joint	Yes	/		
	44.1	joint	Yes	/		
	52.4	joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
52.4		Rebar Exposed	Yes	3 /		
						
60.7	joint		Yes	/		
						
60.7		Infiltration	Yes	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
63.4		Infiltration	Yes	/		LIFT POINT INFILTRATING
						
68.3		joint	Yes	/		
						
71.4		Infiltration	Yes	12 /		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
76.6	joint		Yes	/		
						
80.2	Infiltration		Yes	/		
						
84.3	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
92.3		Joint - Gasket	Yes	/		
						
100.6		joint	Yes	/		
						
108.5		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	111.1	Infiltration	Yes	/		
	116.0	joint	Yes	/		
	124.4	joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	124.4	Infiltration	Yes	12 /		
	133.2	joint	Yes	/		
	141.1	joint	Yes	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
149.2	joint		Yes	/		
						
157.0	joint		Yes	/		
						
165.2	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
172.6		joint	Yes	/		
						
172.6	60.9	Crack -Major	Yes	6 /		
						
180.9		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
188.8	joint		Yes	/		
						
196.8	joint		Yes	/		
						
205.7	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
213.7	joint		Yes	/		
						
221.3	joint		Yes	/		
						
229.7	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
229.7		End of Pipe	Yes	12 /		
						
233.5		End of Pipe	Yes	/		
233.5		STOP	Yes	/		

**EP-4810**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images


Mainline ID: Y-EP4810	Project Name: York County	Start date/time: 1/16/2020 7:47:05 AM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: EXDI#36	Depth US:	Downstream node: EXCB4807	Depth DS:	Asset length: 217.2	Extra:
---------------------------	-----------	------------------------------	-----------	------------------------	--------

Comments

---


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
5.8		joint	Yes	/		
						
13.0		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
13.0	204.2	Crack -Major	Yes	12 /		
						
17.1		Infiltration	Yes	12 /		LIFT POINT NOT GROUDED
						
20.7		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
29.0	joint		Yes	/		
						
37.6	joint		Yes	/		
						
44.7	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
53.1	joint		Yes	/		
						
61.4	joint		Yes	/		
						
69.2	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
76.5	joint		Yes	/		
						
85.1	joint		Yes	/		
						
93.3	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
101.2	joint		Yes	/		
						
109.8	joint		Yes	/		
						
109.8	Grouted		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
109.8		Joint - Infiltration	Yes	8 /		
						
117.8		joint	Yes	/		
						
125.7		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
133.2	joint		Yes	/		
						
142.0	joint		Yes	/		
						
149.8	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
158.4		joint	Yes	/		
						
158.4	58.8	Crack -Major	Yes	6 /		
						
165.9		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
174.1	joint		Yes	/		
						
182.0	joint		Yes	/		
						
190.1	joint		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
198.0	joint		Yes	/		
						
205.9	joint		Yes	/		
						
205.9	Grouted		Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
214.0		joint	Yes	/		
217.2		End of Pipe	Yes	/		
217.2		STOP	Yes	/		

**EP-6001**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: EP6001	Project Name: York County	Start date/time: 1/16/2020 12:06:37 PM	Weather: Dry	Operator: Adam Knight	
Upstream node: OP6001	Depth US:	Downstream node: EXCB6001	Depth DS:	Asset length: 40.0	Extra:
Comments					

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START AGAINST FLOW	Yes	/		
						
2.6	0.7	Crack -Major	Yes	3 /		
						
3.3		joint	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	9.3	joint	Yes	/		
	16.7	joint	Yes	/		
	24.7	Grouted	Yes	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
33.0	joint		Yes	/		
						
40.0	End of Pipe		Yes	/		
						
40.0	STOP		Yes	/		

**EP-6002**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP6002	Project Name: York County	Start date/time: 1/16/2020 11:01:38 AM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	--	-----------------	--------------------------

Upstream node: OP6004	Depth US:	Downstream node: EXCB6002	Depth DS:	Asset length: 44.1	Extra:
--------------------------	-----------	------------------------------	-----------	-----------------------	--------


Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
----------	--------	------	----------	------------	----------	---------

2.5	START WITH FLOW	No	/		
-----	-----------------	----	---	--	--



3.4	joint	No	/		
-----	-------	----	---	--	--



11.2	joint	No	/		
------	-------	----	---	--	--

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	19.4	joint	No	/		
	26.8	joint	No	/		
	34.5	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
34.5	chip		No	8 /		
						
44.1	End of Pipe		No	/		
						
44.1	STOP		No	/		

**EP-6003**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com


## Observation Report with Still Images

Mainline ID: Y-EP6003	Project Name: York County	Start date/time: 1/16/2020 11:16:07 AM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXCB6002	Depth US:	Downstream node: OP6003	Depth DS:	Asset length: 17.0	Extra:

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
4.8		joint	No	/		
						
4.8		Surface Damage	No	12 /		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
12.9		joint	No	/		
						
17.0		End of Pipe	No	/		
						
17.0		STOP	No	/		

**EP-6004**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP6004	Project Name: York County	Start date/time: 1/16/2020 12:19:24 PM	Weather: Dry	Operator: Adam Knight	
Upstream node: EXCB6001	Depth US:	Downstream node: OP6002	Depth DS:	Asset length: 12.0	Extra:

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.5		START WITH FLOW	No	/		
						
4.8		joint	No	/		
						
11.5		Crack- Minor	No	/		GROUT CRACKING

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
12.0		End of Pipe	No	/		
						
12.0		STOP	No	/		

**EP-4811**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images

Mainline ID: Y-EP4811	Project Name: York County	Start date/time: 1/16/2020 8:28:52 AM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: EXCB4807	Depth US:	Downstream node: OP4811	Depth DS:	Asset length: 85.0	Extra:
----------------------------	-----------	----------------------------	-----------	-----------------------	--------

Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
----------	--------	------	----------	------------	----------	---------

2.5		START WITH FLOW	No	/		
-----	--	-----------------	----	---	--	--



2.5	82.5	Crack -Major	No	12 /		
-----	------	--------------	----	------	--	--



5.0		joint	No	/		
-----	--	-------	----	---	--	--

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	12.2	joint	No	/		
	20.0	joint	No	/		
	27.7	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
36.0	joint		No	/		
						
43.7	joint		No	/		
						
51.9	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
60.0	joint		No	/		
						
68.3	joint		No	/		
						
68.3	Grouted		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	76.3	Grouted	No	/		
	83.9	Grouted	No	/		
	85.0	End of Pipe	No	/		

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
85.0	STOP	No	/			

**EP-8401**

**EP-1200.1**



**EP-1200.2**



**EP-1500**



**EP-1809**



**EP-1810**



**EP-1831**



**ECMP-1800**



**EDPI-3600**

AET Services  
 623 Rices Creek Road  
 Liberty, SC 29657  
 1-844-8TOPGUN  
 www.aettopgun.com

## Observation Report with Still Images



Mainline ID: Y-EP3600	Project Name: York County	Start date/time: 1/16/2020 3:01:44 PM	Weather: Dry	Operator: Adam Knight
--------------------------	------------------------------	---	-----------------	--------------------------

Upstream node: OP3601	Depth US:	Downstream node: EXDI#31	Depth DS:	Asset length: 98.1	Extra:
--------------------------	-----------	-----------------------------	-----------	-----------------------	--------


Comments

---

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
2.0		joint	No	/		
						
2.0	96.1	Crack -Major	No	12 /		MULTIPLE
						
2.5		START WITH FLOW	No	/		

## Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	5.3	joint	No	/	/	/
	8.6	joint	No	/	/	/
	12.9	joint	No	/	/	/


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	16.9	joint	No	/		
	21.2	joint	No	/		
	25.4	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	29.0	joint	No	/		
	33.3	joint	No	/		
	37.8	joint	No	/		




### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
41.5	joint		No	/		
						
46.1	chip		No	9 /		
						
49.5	joint		No	/		



### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
53.8	joint		No	/		
						
58.4	joint		No	/		
						
62.1	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	66.3	joint	No	/		
	70.2	joint	No	/		
	71.7	Crack -Multidirectional	No	9 /		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
	73.2	Crack	No	3 /		
	74.5	joint	No	/		
	78.3	joint	No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
82.3	joint		No	/		
						
86.5	joint		No	/		
						
90.6	joint		No	/		

### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
94.7	joint		No	/		
						
94.7	Broken		No	5 /		
						
98.1	End of Pipe		No	/		


### Observations

Distance	Length	Code	Reversed	Clock Pos.	Severity	Comment
						
98.1	STOP	No	/			


**EP-3601**

## Main Inspection with Pipe-Run Graph and Images


Project Name: <b>York County</b>		Mainline ID: <b>EP3600</b>		City: <b>York, SC</b>		Address: <b>177 NB</b>	
Start date/time: <b>1/27/2020</b>		Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>	Surface condition: <b>Asphalt</b>		Weather: <b>Dry</b>
Direction: <b>Downstream</b>		Surveyed footage: <b>96.1</b>		Operator: <b>Alex Barlet</b>		Comments	




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments
Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>		




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
Direction: Downstream	Surface condition: Asphalt	Weather: Dry	Comments
Surveyed footage: 96.1	Operator: Alex Barlet		




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments




Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments




Project Name: York County	Mainline ID: EP3600	City: York, SC	Address: 177 NB
Start date/time: 1/27/2020	Pipe width: 12	Pipe height: 36	Pipe type: Concrete Reinforced
			Surface condition: Asphalt
			Weather: Dry
Direction: Downstream	Surveyed footage: 96.1	Operator: Alex Barlet	Comments



Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
Direction: <b>Downstream</b>	Surface condition: <b>Asphalt</b>	Weather: <b>Dry</b>	Comments:
Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>		



Project Name: <b>York County</b>	Mainline ID: <b>EP3600</b>	City: <b>York, SC</b>	Address: <b>177 NB</b>
Start date/time: <b>1/27/2020</b>	Pipe width: <b>12</b>	Pipe height: <b>36</b>	Pipe type: <b>Concrete Reinforced</b>
			Surface condition: <b>Asphalt</b>
			Weather: <b>Dry</b>
Direction: <b>Downstream</b>	Surveyed footage: <b>96.1</b>	Operator: <b>Alex Barlet</b>	Comments



**EP-4801**



**ECMP-4800**

