

US 1 Replace Bridge over I-20 - Pipe Culvert Inspection Recommendations

Pipe ID	Alignment	Station	# of Barrels	Pipe Size (D or WxH)	Measured Length (ft) during Field Survey	Recommendations for Pipe Based on Video Inspection Report
EP-0101	US1	351+65	1	N/A	N/A	Replace.
EP-0102	Stoneridge Dr.	US1 INTX	1	36"	108	Replace or retain, clean, and seal/line.
EP-0106	US1	332+79	1	24"	150	Replace.
EP-0107	WB Loop	Unknown	1	N/A	N/A	Replace.
EP-0108	EB Loop	363+43	1	18"	62	Retain and clean.
EP-0111	Cedar Rd.	Unknown	1	42"	51	Replace or retain, clean, and repair joints showing separation.
EP-0112	Cedar Rd.	Unknown	1	36"	46	Replace or retain and repair joints showing separation.
EP-0113	US1	302+32	1	24"	61	Replace.
EP-0115	US1	299+25	1	18"	>5	Replace.
EP-0116	US1	295+88	1	36" & 18"x 36"	57	Repair joints and and holes in box culvert section.
EP-0116A	US1	295+88	1	36"	13	Retain.
EP-0117	US1	293+15	1	24"	>37	Replace.