

DM0306

November 14, 2006

MEMORANDUM TO TEAM LEADERS AND CONSULTANTS

SUBJECT: Design Manual Errata

Section Properties for Prestressed Concrete Beams

Figure 15.5-1 (on pages 15-30 and 15-31) of the *SCDOT Bridge Design Manual* shows dimensions and section properties for prestressed concrete beams. The section properties for the Type I Modified Beam and the 54" Modified Bulb-Tee Beam are not correct. The correct values are indicated below:

Type I Modified Beam $I = 26.495 \text{ in}^4$

54" Modified Bulb-Tee $A = 707 \text{ in}^2$ W = 737 plf $Y_{TOP} = 26.21$ " $Y_{BOT} = 27.79$ "

 $I = 277,560 \text{ in}^4$

Please make the appropriate corrections to your copy of the Manual.

Mitchell D. Metts, P.E. Bridge Design Engineer

Nitchell

cc: Assistant Bridge Design Engineers
Bridge Construction Engineer
Bridge Maintenance Engineer
FHWA Structural Engineer

File: PC/BWB

