Video Pipe Detail Report

M&H Project Number:	R3286900-141416.01
Client / State Project Number:	
Project Name:	I-85 CHEROKEE COUNTY DB PREP-(MM 80-96)
Project Address:	CHEROKEE COUNTY, SC
Client:	SCDOT

Pipe ID:	1623+00	**Date of Inspection:**	4/14/2015
Length of Pipe (ft):	128	**Type of Pipe:**	RCP
Pipe Diameter (in):	18	**Pipe Location:**	See Pipe ID

Summary of Issues

Damage Type:	**N/A**
Location of Damage (ft):	**4**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:00:08**

Comments: **Start of pipe**

Damage Type:	**N/A**
Location of Damage (ft):	**72**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:09:55**

Comments: **Drop inlet**



Damage Type:	**Gapped Joint**
Location of Damage (ft):	**124**
Crack/Break Width (in):	**5**
Video Cue Time:	**0:17:15**

Comments: **Broken bell. Approx. 5" of soil can be seen.**

Mead & Hunt

Video Pipe Detail Report

M&H Project Number:	R3286900-141416.01
Client / State Project Number:	
Project Name:	I-85 CHEROKEE COUNTY DB PREP-(MM 80-96)
Project Address:	CHEROKEE COUNTY, SC
Client:	SCDOT

Pipe ID:	1623+00	**Date of Inspection:**	4/14/2015
Length of Pipe (ft):	128	**Type of Pipe:**	RCP
Pipe Diameter (in):	18	**Pipe Location:**	See Pipe ID

Summary of Issues

Damage Type:	**N/A**
Location of Damage (ft):	**128**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:18:20**

Comments:

End of pipe in drop inlet at shoulder.

Mead & Hunt