

REQUESTOR L. GibsonROAD I-77

FWD FILE #

LANE/DIRECTION ONBCOUNTY RichlandOPERATORS ES, RJDATE 8/6/14NB Travel Lane

DISTANCE	CORE #	DEPTH	BASE	COMMENTS
0.00	1	12.5	Macadam	@ E.R. 15B
0.80	2	14.5	" "	@ E.R. 16
1.08	3	12.0	" "	Before Flipping
1.30	4	12.0	" "	@ Bridge
1.80	5	14.75	" "	@ Exit 17 Bypass Sign on R.H.
2.20	6	15.0	" "	@ Exit 17 Bypass Sign
2.58	7	13.2	" "	Just Before Concrete Barrier
3.00	8	9.0"	Con MOD	6" Con MOD Just on Concrete
	$\frac{3}{8} \text{ DB} = 1.4833$	Avg - 13.35	$\frac{1}{2} \text{ Avg} = 6.675$	
SB				RT. Shoulder SB Lane
0	1	7.8	MAC.	1st test at MM 22
0.855	2	8.5	" "	
1.6	3	7.5	" "	
2.4	4	8.7	" "	
3.3	5	7.7	" "	
4.0	6	7.0	" "	
5.0	7	6.8	" "	
6.1	8	7.8	" "	
6.9	9	9.0	" "	Last test at MM 15
	$\frac{3}{8} \text{ DB} = 0.87407$	Avg - 7.967	$\frac{1}{2} \text{ Avg} = 3.933$	
NB				RT Shoulder NB Lane
0	1	7.3	Sand clay	1st Test at MM 15.0 NB
0.8	2	7.5	" "	
1.1	3	5.1	" "	
1.9	4	7.9	" "	Last Test at MM 16.9.
	$\frac{3}{8} \text{ DB} = 0.7722$	Avg - 6.95	$\frac{1}{2} \text{ Avg} = 3.475$	
Weather	Base - 9"			
8-5 - 84				
8-4 - 82				
8-3 - 79				
8-2 - 74				
8-1 - 77				
Avg - 79.2				







