

955 Park Street Post Office Box 191 Columbia, South Carolina 29202-0191 Office of the Director (803) 737-1302 • Fax (803) 737-2038

Deputy Director of Engineering (803) 737-1314 • Fax (803) 737-2038

Deputy Director of Finance and Administration (803) 737-1240 • Fax (803) 737-1719

Deputy Director of Mass Transit (803) 737-9720 • Fax (803) 737-9739

DM0697

June 17, 1997

MEMORANDUM TO GROUP LEADERS & CONSULTANTS

SUBJECT:

Splicing column reinforcing

An allowable splice in the main (vertical) steel should be detailed above the shaft and below the cap between the confinement regions in the column. The confinement regions are as defined in design memorandum DM0391. See Figure 1 on the attachment.

This memorandum supplements design memorandum DM0495.

Randy R. Cannon

Bridge Design Engineer

Attachment:

cc: Assistant Bridge Design Engineers




Figure 1