Video Pipe Detail Report

M&H Project Number:	R3286900-141416.01
Client / State Project Number:	
Project Name:	I-85 CHEROKEE COUNTY DB PREP-(MM 80-96)
Project Address:	CHEROKEE COUNTY, SC
Client:	SCDOT

Pipe ID:	1728+00 NB	**Date of Inspection:**	4/22/2015
Length of Pipe (ft):	184	**Type of Pipe:**	RCP
Pipe Diameter (in):	18	**Pipe Location:**	See Pipe ID

Summary of Issues

Damage Type:	**N/A**
Location of Damage (ft):	**4**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:00:15**

Comments: **Start of pipe**

Damage Type:	**Dislocations**
Location of Damage (ft):	**20**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:02:00**

Comments: **Joint separation. Can't measure gap due to slope of pipe.**

Damage Type:	**Gapped Joint**
Location of Damage (ft):	**24**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:02:30**

Comments: **Joint Break with washout in process. Can't measure gap due to slope of pipe.**

Mead & Hunt

Video Pipe Detail Report

M&H Project Number:	R3286900-141416.01
Client / State Project Number:	
Project Name:	I-85 CHEROKEE COUNTY DB PREP-(MM 80-96)
Project Address:	CHEROKEE COUNTY, SC
Client:	SCDOT

Pipe ID:	1728+00 NB	**Date of Inspection:**	4/22/2015
Length of Pipe (ft):	184	**Type of Pipe:**	RCP
Pipe Diameter (in):	18	**Pipe Location:**	See Pipe ID

Summary of Issues

Damage Type:	**Gapped Joint**
Location of Damage (ft):	**28**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:03:07**

Comments: **Joint break with washout in process. Can't measure gap due to slope of pipe.**

Damage Type:	**N/A**
Location of Damage (ft):	**184**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:24:00**

Comments: **End of pipe in drop inlet.**

Mead & Hunt