Video Pipe Detail Report

M&H Project Number:	R3286900-141416.01
Client / State Project Number:	
Project Name:	I-85 CHEROKEE COUNTY DB PREP-(MM 80-96)
Project Address:	CHEROKEE COUNTY, SC
Client:	SCDOT

Pipe ID:	1404+90	**Date of Inspection:**	4/9/2015
Length of Pipe (ft):	N/A	**Type of Pipe:**	RCP
Pipe Diameter (in):	18	**Pipe Location:**	See Pipe ID

Summary of Issues

Damage Type:	**N/A**
Location of Damage (ft):	**8**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:00:15**

Comments: **Start of pipe**

Damage Type:	**N/A**
Location of Damage (ft):	**124**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:14:20**

Comments: **Drop inlet that appears to be covered**

Damage Type:	**N/A**
Location of Damage (ft):	**128**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**0:15:50**

Comments: **Pipe changed from 18" to 24"**

Mead & Hunt

Video Pipe Detail Report

M&H Project Number:	R3286900-141416.01
Client / State Project Number:	
Project Name:	I-85 CHEROKEE COUNTY DB PREP-(MM 80-96)
Project Address:	CHEROKEE COUNTY, SC
Client:	SCDOT

Pipe ID:	1404+90	**Date of Inspection:**	4/9/2015
Length of Pipe (ft):	N/A	**Type of Pipe:**	RCP
Pipe Diameter (in):	18	**Pipe Location:**	See Pipe ID

Summary of Issues

Damage Type:	**N/A**
Location of Damage (ft):	**144**
Crack/Break Width (in):	**N/A**
Video Cue Time:	**N/A**

Comments: **Pipe entering from side of pipe. Can't continue due to incoming pipe.**

Mead & Hunt